



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77664
Promised Date:
20 AUG 25

CUSTOMER WORK ORDER

WO #: 77664

Customer: 56151 - GILBERT, BRADLEY -
812-589-5731

Tag:

Author: BH

Location: 1001 CHECK PREAUTH

Stock #: 11560

Stock Desc: 2025 TT COACHMEN

CATALINA SUMMIT 261BH

Chassis #: 5ZT2CARB7SU045635

Serial #: 5ZT2CARB7SU045635

Mileage:

Licence:

Invoice #:

Date In: 27 AUG 25

Promised: 29 AUG 25

Date Sched:

Completed: 29 SEP 25

Warr. Date: 29 AUG 25

Job #FPDINTT - Internal

Transferred to BAS*77735 on 04 SEP 25

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Subtotal for Job #FPDINTT: 0.00

Job #EQUALIZER1000 - Internal

Transferred to BAS*77735 on 04 SEP 25

Estimate amount was 0.00

INSTALL 1000# EQUALIZER HITCH

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #EQUALIZER1000: 0.00

Job #DELUXE - Internal

Transferred to BAS*77735 on 04 SEP 25

Estimate amount was 0.00

DELUXE STARTER KIT

Customer #: 56151
GILBERT, BRADLEY



Subtotal for Job #DELUXE: 0.00

Job #1 - Warranty

COMPLAINT: NO CHANNELS ON THE TV

CAUSE: Antenna no signal

CORRECTION: After inspection the tv power booster not working so I replaced it and it works properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00

Parts

Part #	Description	Qty	Price	Total
F100370436	WALL PLATE, 2 TV-OUT AMPLIFIED SIGNA	1.00	12.77	12.77

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-WALL PLATE	1.00	15.83	15.83

Subtotal for Job #1: 84.10

Job #2 - Warranty

COMPLAINT: JACK NOT WORKING

CAUSE: Bad ground contact

CORRECTION: Turned the jack light on and it lit then pushed the button for the jack to go up or down and the jack light went out. Checked the wire at the circuit breaker by removing it and connecting it directly to the battery and still got nothing from the jack motor. Checked the ground where the jack bolts to the coupler. There were washers on top of the star washers. Unbolted one of the bolts and removed the washer but left the star washer in place. Tightened the bolt then pushed the button for the jack motor and it works. With the washer in place, there was not enough ground contact.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	55.50

Subtotal for Job #2: 55.50

Parts Total:	12.77
Labour Total:	111.00
Sublet Total:	0.00
Extras Total:	15.83

WORK ORDER TOTAL: 139.60

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 29 Sep 2025

W/O: 77664
Promised Date: 29 AUG 25



Customer #: 56151
GILBERT, BRADLEY

