



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79035
Promised Date:
19 FEB 26



CUSTOMER WORK ORDER

WO #: 79035

Customer: 56102 - CRAVER, BRIAN -
585-703-0362

Tag:

Author: BH

Location: 0224 CHECK PREAUTH

Stock #: 11597

Stock Desc: 2025 TT COACHMEN

CATALINA SUMMIT 221EPIC

Chassis #: 5ZT2CALB1SU046143

Serial #: 5ZT2CALB1SU046143

Mileage:

Licence:

Invoice #:

Date In: 16 FEB 26

Promised: 19 FEB 26

Date Sched:

Completed: 24 FEB 26

Warr. Date: 19 FEB 26

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery and a new battery box strap. Exterior inspection looks good. Awning fabric and hardware looks and works properly Awning lights work properly. Roof inspection found a couple voids in the sealer that I filled with dicor self-leveling roof good now. Interior inspection hooked up to city water and flushed out all the lines. Stove works properly microwave works properly refrigerator works properly ac works properly furnace works properly water heater works properly. Put water in fresh tank and flushed out all the lines. Tv antenna works properly

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
55364	55364 REPLACEMENT BATTERY BOX STRAP	1.00	N/C	N/C
17-0181	ZIP 6FT BREAKAWAY CABLE AND PIN	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #HANDLE - Internal

COMPLAINT: INSTALL LEND-A-HAND

CHOOSE BLACK OR WHITE

CAUSE: Install a led a hand

CORRECTION: Put budle tape where screws are going shot the 6 screws that came with the handle. And then i sealed it with clear silicone. Good to go

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
2603892	GRAB HANDLE W/GRIP - BLACK - LEND A	1.00	N/C	N/C



Customer #: 56102
CRAVER, BRIAN





Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
PARTS	UNINVENTORIED PARTS	0.00	N/C	N/C
Subtotal for Job #HANDLE:				0.00

Job #SWAP - Internal

COMPLAINT: SWAP CUSTOMER'S HITCHWORK

CAUSE: Hitch work

CORRECTION: Installed new blue ox brackets on unit. And removed old brackets off trade in and put in customers box. Got hitch adjusted for new unit good to go

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JTW	N/C

Parts				
Part #	Description	Qty	Price	Total
14-0823	TITAN PULL PIN & CLIP	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #SWAP:				0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
 WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Turned valve to winterize and pumped solution through the pump to the bathroom shower hot and cold until solution was there then repeated for bathroom faucet and toilet and kitchen sink. And turned water heater bypass valves to winterize mode. And depressed city water inlet and drained black tank and gray tank and fresh tank. Used 2 gallons of winterize solution

Labor				
Code	Description		Mechanic	Total
Z990	WINTERIZE UNIT		JTW	N/C

Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #1 - Warranty

COMPLAINT: WATER HEATER WILL NOT STAY LIT. FLAME IS VERY WEAK

CAUSE: Water heater not burning hot enough

CORRECTION: Took the burner tube off and made sure no debris was in the tube. Took lp line off valve and did a lp test on that line with furnace running and it was real low. Checked inside to make sur hose wasn't pinched it was good. Went under the unit and found the line was pinched at the manifold so i pulled



some of the lp hose down from inside and turn the manifold so the line would not be pinched and tested my lp connection and no leaks and turned on the water heater and it ran properly

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	222.00
Subtotal for Job #1:			222.00

Job #2 - Warranty

COMPLAINT: THE WALL BOARD IN 2 PLACES IS LOOSE

CAUSE: Paneling and rubber trim

CORRECTION: Popped staples in the paneling to hold it in place below the window and in the corner. Used a heat gun to soften the rubber trim so it would lay flat. Took pictures of the process.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	55.50
Subtotal for Job #2:			55.50

Parts Total: 0.00
Labour Total: 277.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 277.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 24 Feb 2026

W/O: 79035
Promised Date: 19 FEB 26



Customer #: 56102
CRAVER, BRIAN

