

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD
EVANSVILLE, IN 47725
USA

CLAIM STATUS Authorized
CLAIM 2614122
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2FEXB6SW030243
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 320 / 320
ITEM # FET324RLDS-320
DEALER RO # 79158
CLAIM START DATE 03/19/2026
CLAIM END DATE 01/01/1900

Labor rate: \$195.00

OWNER INFORMATION

GREGORY DAWN ALVEY
122 DORSEY ST
Corydon, KY 42406
USA

Retail Date of Purchase 03/09/2026

WARRANTY EXPIRATION DATE

03/09/2027

Claim Line Details

Labor

Line# 1 Operation Code Operational Description
20-69-01-00-000707 Compartment Door Gasket - Exterior/Compartment Doors/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2026-03-19 09:36:29 :: REPLACE TORN GASKET AROUND OUTDOOR KITCHEN Outside kitchen door gasket ripped Took off old gasket cleaned area. And installed the new gasket. Door shuts properly. Good to go

Model# Dlr Sub Hrs 0.30 Sub Labor Amt \$58.50
Serial# Appr Hrs 0.30 Appr Labor Amt \$58.50

Notes

Labor

Line# 2 Operation Code Operational Description
50-134-01-00-001443 LP Regulator - Includes Leak Test - LP Gas/LP Gas System/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2026-03-19 09:37:16 :: THE LP REGULATOR IS ADJUSTED AS FAR AS IT WILL GO, AND IT IS STILL NOT IN FACTORY SPECIFICATIONS. Regulator adjustment bottomed out at 9.9 WC with 50% load Removed and replaced regulator with teflon tape on all non-flared fittings. Bubble tested with no leaks present

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$97.50
Serial# Appr Hrs 0.50 Appr Labor Amt \$97.50

Notes

Labor

Line# 3 Operation Code Operational Description
70-167-01-00-001997 Water Heater Door - Appliances/Water Heater (Suburban)/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2026-03-19 09:41:28 :: WATER HEATER DOOR IS RUSTED Water heater door Water heater door had rust on it in several spots that i removed the whole door and replaced it with a new one. Good to go

Model# st45 Dlr Sub Hrs 0.30 Sub Labor Amt \$58.50
Serial# na Appr Hrs 0.30 Appr Labor Amt \$58.50

Notes

Submitted

Labor Amt\$214.50
Parts & Freight\$0.00
Total\$214.50

Approved

Labor Amt\$214.50
Parts & Freight\$0.00
Total\$214.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.