

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD
 EVANSVILLE, IN 47725
 USA

Labor rate: \$170.00

OWNER INFORMATION

MARIA PEREZ
 2013 PEGGY DR
 Henderson, KY 42420
 USA

CLAIM STATUS Authorized
 CLAIM 2119787
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TCKZ21PX160923
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 017 / 017A
 ITEM # ACKT243TR
 DEALER RO # 75382
 CLAIM START DATE 11/12/2024
 CLAIM END DATE 01/01/1900

Retail Date of Purchase 04/08/2024 WARRANTY EXPIRATION DATE 04/08/2025

Claim Line Details

Labor

Line# 1 Operation Code Operational Description
 30-100-01-00-001035 Cabinet Door - Interior/Cabinetry/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2024-11-12 08:43:55 :: THE CABINET DOOR IS NOT ON RIGHT THE CABINET DOOR IN THE BED ROOM Door not on right I looked at all doors in bed room and found one that is a little more open at the top than the other
 Model# Dlr Sub Hrs 0.40 Sub Labor Amt \$68.00
 Serial# Appr Hrs 0.40 Appr Labor Amt \$68.00
 Notes

Labor

Line# 2 Operation Code Operational Description
 30-103-24-00-001125 Linoleum - Interior/Flooring/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2024-11-12 08:45:54 :: THE FLOOR HAS A SPOT IN THE LIVING ROOM IN FRONT OF THE FIRE PLACE FOUND SPOT IN FLOOR SUBLET WORK TO FIBERNEW
 Model# Dlr Sub Hrs 1.50 Sub Labor Amt \$255.00
 Serial# Appr Hrs 1.50 Appr Labor Amt \$255.00
 Notes
 Need a cause for the damage
 don't know not there when it happened but the slide does not have any groves or marks on the bottom of it
 Per Dealer request
 CHANGED FROM SUBLET TO TIME
 Authorized as requested

Submitted	Labor Amt	\$323.00	Approved	Labor Amt	\$323.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$323.00		Total	\$323.00

DEALER _____ DATE _____
 SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE
 All repairs described have been inspected and are satisfactory.