FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	1054928	**CLAIM STATUS**	Paid
LINK FORD & RV MINONG LLC		**CLAIM**	2635157
1025 W HOKAH ST		**CLAIM ORIGIN**	WEB
MINONG, WI 54859		**ORIGINAL CLAIM ID**	
USA		**VIN**	4X4TWDM23LM059016
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	$165.00	**SITE/WAREHOUSE**	004 / 004A
OWNER INFORMATION		**ITEM #**	WDT353FLFB
JACQUELYN BARNARD		**DEALER RO #**	40332
		CLAIM START DATE	04/08/2026
4901 TIOGA ST		**CLAIM END DATE**	04/08/2026
Duluth, MN 55804			
USA			
Retail Date of Purchase	05/16/2020	**WARRANTY EXPIRATION DATE**	05/16/2021

Claim Line Details

Labor

Line# 1

Operation Code
RC-003-13-00-004757

Operational Description
25V682, 2025-545 - MISSING OVERCURRENT PROTECTION - INSPECT & REPAIR - Recall/Electrical/Relocate/No Tread Code

Complaint, Cause, Correction
Original Note : alix@dealer-advisors.com, 2026-04-08 13:30:03 :: Complaint: Customer states recall - 12 volt is wired directly to battery, lacking over-current protection Cause: Inspected the wiring on the frame and found that the main coach wiring was in wrong location along with the other 2 wires all of them were bolted to the hot side of the breakers. Correction:Took them all off and wired to the other side of the breakers and tested the lights inside camper and everything is working and protected not by the breakers.

Model#		**Dlr Sub Hrs**	0.30	**Sub Labor Amt**	$49.50
Serial#		**Appr Hrs**	0.20	**Appr Labor Amt**	$33.00

Notes
Authorized

Submitted			**Approved**		
	Labor Amt	$49.50		Labor Amt	$33.00
	Parts & Freight	$0.00		Parts & Freight	$0.00
	Total	$49.50		Total	$33.00

DEALER SIGNATURE **DATE**

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER SIGNATURE **DATE**

All repairs described have been inspected and are satisfactory.