Tag Number:_____

Estimate No. 1388
Estimate Date: 1-7-26

Oxidation RV Repair Service
4516 2nd St NW
Albuquerque,NM 87107
505-417-9386
oxidationrv@gmail.com

Customer: Myers RV Center
12024 Central AVE
SE Albuquerque NM
8712

Make: TRACER Model: _____

Year: 25 VIN: 5ZT2TRHB2SB525920

Estimate		Amount
Repair stress cracks on Driver Side rear slide out track wall		
Mask unit	1.0	$130.00
Repair fiberGloss	3.0	
Remove Decal	.5	
Sand	1.5	
PAINT	2.5	
Clear	1.0	
Color Sand Buff	1.0	
Paint Mix		367.5
Waste Disposal		10.00
Shop Supplies		10.00
Labor		808.5
Parts		
Misc.		
Subtotal		
Sales Tax		
Total		$1,226.00

Adjuster Name: _____ Claim Number: _____
Telephone No. _____
Customer Signature: _____ Date: _____