



Pre-Authorization

Pre-Reference	2598	Status	Denied
Authorization no.	2		
number	634		
	(PAO		
	3903		
	244)		

Servicing Dealer 8140

Name Tri-AM RV Center of East TN

Address 1202 Idell Rd
Bulls Gap, TN 37711

VIN 4YDFAAU25TZ915030

Retail sold on

Root			Sub	Approved	Actual		Base	
Operation	Description	Sublet	Hours	Hours	hours	Qty	hours	Complaint/Cause/Correction
3202012B	Panel - Interior Wall - Replace	0	0.3	0		1	1	Complaint: Seam tape in the kitchen is brown on color and looks stained compared to other seam tape in the unit Cause: Noted on DAF Correction: Replace the discolored seam tape

KRV – The issue submitted is not considered a warranty defect in materials or workmanship.

For paper claims only use one pre-authorization number per warranty claim form.

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

Root			Sub	Approved	Actual		Base	
Operation	Description	Sublet	Hours	Hours	hours	Qty	hours	Complaint/Cause/Correction
3200112A	Door - Interior Hinged - Repair	0	0.2	0	_____	1	0.2	Complaint: Half bath door has white paint on the front side Cause: Noted on DAF Correction: Clean, color, and blend area KRV – The issue submitted is not considered a warranty defect in materials or workmanship.
3100808A	Cabinet Door - Repair	0	0.2	0	_____	1	0.2	Complaint: Bathroom cabinet door chipped on top, left corner Cause: Noted on DAF Correction: Fill, color, blend, and clean area KRV – The issue submitted is not considered a warranty defect in materials or

For paper claims only use one pre-authorization number per warranty claim form.

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

Root			Sub	Approved	Actual		Base	
Operation	Description	Sublet	Hours	Hours	hours	Qty	hours	Complaint/Cause/Correction
Pre-Authorization number: PREAUTH8634				0				

For paper claims only use one pre-authorization number per warranty claim form.

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.