



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 26336



WO #: 26336 (Appointment Date: 05 NOV 2025 - Time: 02:00pm)

Customer: 67026 - BURCHETT, ROBERT  
Address: 4809 TAZWELL HWY  
SNEEDVILLE, TN  
37869

Home Phone: (423) 300-9831

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11027

Stock Desc: 2025 TT KZ-RV SPORTSMEN SEL

221RKSL

Model: 221RKSL

Serial #: 4EZTU2225S5096773

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 12 SEP 25

Date In: 05 NOV 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 12 SEP 25

**Job #2 - Warranty**

COMPLAINT: AWNING ARM IS BENT CUST STATED HE SAID YOU COULD TELL THE ARM HAS BEEN ADJUSTED PRIOR

CORRECTION: NO ISSUE AT THIS TIME

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: THE WOOD ON THE REAR OF THE UNIT IS STICKING OUT IN THE MIDDLE. WOOD NOT INSTALLED FLUSH AND CAUSING IT TO BULGE OUT.

CAUSE: TECH DETERMINED THE WOOD SUBSTRATE UNDER THE ROOF MEMBRANE WAS NOT PROPERLY SECURED OR FINISHED AT THE FACTORY. WOOD WAS NOT CUT TO THE CORRECT DIMENSIONS CAUSING WEAR TO THE TPO MATERIAL.

CORRECTION: REMOVE AND REINSTALL A/C, VENTS, ALL RAILS, GUTTER SPOUTS, SEWER VENTS ETC. CORRECT WOOD TO FIT, REPLACE ROOF MEMBRANE WITH NEW ONE AND RESEAL ALL AREAS.

LABOR 30.0

**Subtotal for Job #3: 0.00**

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X \_\_\_\_\_

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 04 Dec 2025

Customer Signature : \_\_\_\_\_

Customer #: 67026  
BURCHETT, ROBERT

