



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26707



WO #: 26707 (Appointment Date: 10 FEB 2026 - Time: 10:30am)

Customer: 93437 - KOLESSAR, SCOTT
Address:

Home Phone: 412-997-8153

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #:
Stock Desc: 2026 FOREST RIVER XLR
Model:
Serial #: 4X4TXLJ2XTF171151
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 10 FEB 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - External

sc to mammoth ridge 100.00

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

COMPLAINT: WATER HEATER IS LEAKING

CAUSE: BRASS FITTING COMPONENT FAILED AND IS ALLOWING THE WATER HEATER TO LEAK

CORRECTION: REPLACE WATER HEATER AND TEST
LABOR FOR REPLACEMENT AND DIAG

1.50

Subtotal for Job #2: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 93437
KOLESSAR, SCOTT



Customer Signature : _____

Date: 11 Feb 2026

