



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 25933 MALONE, DALE



Estimate: 25933

Customer: 62790 - MALONE, DALE
Address: 201 WEST LANE ST
CHURCH HILL, TN
37642

Home Phone: 423-367-6601

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #: 9536

Stock Desc: 2016 A FOREST RIVER MIRADA
31FW

Model: 31FW

Serial #: 1F66F5DY2G0A03954

Chassis #: 1F66F5DY2G0A03954

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 05 JUL 19

Date In: 15 AUG 25

Promise Date: 30 SEP 25

Promise Time: 09:00am

Schedule Date:

Completed:

Warr. Date: 05 JUL 19

Job #1 - External

CS THAT THE TRIM ALONG THE TOP OF DRIVER SIDE CHECK AND ADVISE

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

CS THAT THE MICROWAVE KEEP COMING LOOSE CHECK AND ADVISE

Subtotal for Job #2: 0.00

Job #3 - External

CS THAT THE ENTRY DOOR LOCK NEEDS TO BE ADJUSTED

Subtotal for Job #3: 0.00

Job #4 - External

NEED TO EXTRA KEYS FOR THE ENTRY LOCK

Subtotal for Job #4: 0.00

Job #5 - External

CS THAT THE 7 WAY PLUG HAS NO POWER COMING OUT OF THE PLUG CHECK AND ADVISE

Subtotal for Job #5: 0.00

Job #6 - External

CS THAT THE CAMERA ON THE DRIVER SIDE IS INOP CHECK AND ADVISE



Subtotal for Job #6: 0.00

Job #7 - External

CS THAT THEY WANTS THE GASKET REPLACED ON THE ENTRY DOOR CHECK AND ADVISE CAN
HERE WIND AND CARS DRIVE BY WHEN TRAVELING

Subtotal for Job #7: 0.00

Job #8 - External

CS THAT WHEN THE DRIVERS SIDE SLIDE COMES IN IT PULLS THE LOWER FACIA AWAY FROM
THE SIDE OF THE SLIDE

Subtotal for Job #8: 0.00

Job #9 - External

QUOTE ON AWNING FABRIC

Subtotal for Job #9: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 21 Aug 2025

