



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 26065 BLACKBURN,
ROBERT



Estimate: 26065 (Appointment Date: 12 SEP 2025 - Time: 03:00pm)

Customer: 83926 - BLACKBURN, ROBERT
Address: 654 CANEY CREEK RD
ROGERSVILLE, TN
37857

Home Phone: 423-293-9533

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #: 10576
Stock Desc: 2022 TT FOREST RIVER
ROCKWOOD ULTRA 2608BS
Model: 2608BS
Serial #: 4X4TRLB21NZ182467
Chassis #:
Mileage: 0
Key #: 4135
Req'n #:
License #:
Trim:

Purchase Date: 21 APR 22
Date In: 12 SEP 25
Promise Date: 30 SEP 25
Promise Time: 09:00am
Schedule Date:
Completed:
Warr. Date: 21 APR 22

Job #WINT2 - External

WINTERIZE-TT/CLASS C

Due to the winterization process, most refrigerator filters and water filters will need to be replaced. Because of the variability of filters, customers will be responsible for ordering/supplying the replacement filter for your unit at time of dewinterization in the spring.

Because of the number of different filters being used by manufacturers, Tri-Am RV cannot guarantee that we will have the correct filter in stock at time of the appt. Therefore, we recommend that you either pre-order your filters, or bring them with you at your appointment time.

Initial/Date: _____

Labor

Code	Description	Hours	Rate	Total
SP120140	WINTERIZE FRESH WATER SYSTEM	1	175.00	175.00

Parts

Part #	Description	Qty	Price	Total
13-1639	ANTIFREEZE -50	3	5.39	16.17

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	8.75	8.75

Subtotal for Job #WINT2: 199.92

Job #2 - External

CS THAT THEY WANT THE DAMAGE IN THE REAR CORNER REPLACED

Subtotal for Job #2: 0.00

Job #3 - External

CHECK BIG SLIDE C/S THAT THERE IS SOMETHING STICKING OUT



Subtotal for Job #3: 0.00

Parts Total:	16.17
Labour Total:	175.00
Sublet Total:	0.00
Extras Total:	8.75
Tax Total:	19.49
Estimate Total:	219.41

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 17 Sep 2025

