



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

Estimate: 26185 SIMERLY, MIKE



Estimate: 26185 (Appointment Date: 15 OCT 2025 - Time: 09:00am)

Customer: 89432 - SIMERLY, MIKE
 Address: 202 CRESSWOOD DRIVE
 ROGERSVILLE, TN
 37857

Home Phone: 423-215-8698

Work Phone:
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #:
 Stock Desc: 2022 TT WINEBAGO MICRO MINNIE
 2108DS
 Model: 2108DS
 Serial #: 54CTM2K28N3059234
 Chassis #:
 Mileage:0
 Key #:
 Req'n #:
 License #:
 Trim: 2108TB

Purchase Date:
 Date In: 10 OCT 25
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed:
 Warr. Date:

Job #WINT2 - External
 WINTERIZE-TT/CLASS C

Due to the winterization process, most refrigerator filters and water filters will need to be replaced. Because of the variability of filters, customers will be responsible for ordering/supplying the replacement filter for your unit at time of dewinterization in the spring.

Because of the number of different filters being used by manufacturers, Tri-Am RV cannot guarantee that we will have the correct filter in stock at time of the appt. Therefore, we recommend that you either pre-order your filters, or bring them with you at your appointment time.

Initial/Date: _____

Labor

Code	Description	Hours	Rate	Total
SP120140	WINTERIZE FRESH WATER SYSTEM	1	175.00	175.00

Parts

Part #	Description	Qty	Price	Total
13-1639	ANTIFREEZE -50	3	5.99	17.97

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	8.75	8.75

Subtotal for Job #WINT2: 201.72

Job #2 - External

LEFT FRONT STABLIZER MOTOR NOT WORKING

Subtotal for Job #2: 0.00

Job #3 - External

CUST IS SEEING WATER DRIP FROM THE UNDER BELLY NEAR THE DUMP HOSE. CUST IS THINKING THIS COULD BE A FRESH WATER LEAK



Subtotal for Job #3: 0.00

Job #4 - External

LEAK IS AT THE OUT DOOR SHOWER LOOKS LIKE IT IS LEAKING AT HOT AND COLD BOTH
CUSTOMER STATED
THIS GOES LINE 3

Subtotal for Job #4: 0.00

Job #5 - External

HOT WATER HEATER IS GETTING TO HOT, CUST SAID IT GOES STRAIGHT TO BOIL

Subtotal for Job #5: 0.00

Job #6 - External

CUST CAN'T CONNECT TO THE SPRAY PORT

Subtotal for Job #6: 0.00

Job #7 - External

BLACK TANK HANDLE IS BENT HE PURCHASED ONE HERE IT IS IN THE FRONT LEFT
COMPARTMENT HE STATED IT DON'T FIT IF NOT HE DOES NEED A NEW ONE INSTALLED

Subtotal for Job #7: 0.00

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION
CHECK CAULKING _____
CHECK SKYLIGHTS _____
CHECK ROOF VENTS _____
CHECK LUBE & ANTENNA _____
CHECK SATELLITE _____
CHECK RUBBER _____

Subtotal for Job #ROOFINS: 0.00

Parts Total: 17.97
Labour Total: 175.00
Sublet Total: 0.00
Extras Total: 8.75
Tax Total: 19.67
Estimate Total: 221.39

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 18 Oct 2025

