



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 26193 FANNON, DONALD



Estimate: 26193 (Appointment Date: 13 OCT 2025 - Time: 11:00am)

Customer: 89816 - FANNON, DONALD
Address: 2097 HIGHWAY 81 SOUTH
JONESBOROUGH, TN
37659

Home Phone: (423) 218-8163

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #: 10611

Stock Desc: 2022 FW FOREST RIVER

ROCKWOOD SIGN 8288SB

Model: 8288SB

Serial #: 4X4FRLE28N1901673

Chassis #:

Mileage:

Key #: 4135

Req'n #:

License #:

Trim:

Purchase Date: 23 MAR 23

Date In: 13 OCT 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 23 MAR 23

Job #2 - External

COMPLAINT: WASH

CORRECTION: WASHED UNIT

Other Services

Code	Description	Qty	Price	Total
WASH	WASH COACH	0	200.00	0.00

Subtotal for Job #2: 0.00

Job #1 - External

DINETTE SLIDE POPS WHEN RUNNING OUT AT THE VERY END

Labor

Code	Description	Hours	Rate	Total
Z990	DIAG/REPAIR	1.50	175.00	262.50

Parts

Part #	Description	Qty	Price	Total
00-0495	Awning; Solera Slide Topper	1	508.49	508.49

Subtotal for Job #1: 770.99

Job #ROOFINS - External

COMPLAINT: COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

CORRECTION: ROOF LOOKS GOOD AT THIS TIME RECHECK IN 6 MONTHS



Subtotal for Job #ROOFINS: 0.00

Job #3 - External

ON KITCHEN ISLAND THE 110 OUTLET IS DAMAGED CUS WOULD LIKE QUOTE ON A NEW ONE

Labor

Code	Description	Hours	Rate	Total
Z990	DIAG/REPAIR	0.50	175.00	87.50

Parts

Part #	Description	Qty	Price	Total
55-2599	Receptacle; Decor ; Indoor Use; 125 Volt AC Power; Non Ground Fault Interrupter; Dual Receptacle; Black	1	17.99	17.99

Subtotal for Job #3: 105.49

Job #4 - External

COMPLAINT: BEARING PACK

CORRECTION: REPACKED BEARING NEW SEALS AND CHECKED AND ADJUSTED BRAKES IF NEEDED

Labor

Code	Description	Hours	Rate	Total
Z990	BEARINGS	0	175.00	0.00

Parts

Part #	Description	Qty	Price	Total
010-036-00	OIL SEAL-DOUBLE LIP	0	12.59	0.00
BPC-20	BRAKE CLEANER	0	8.09	0.00

Subtotal for Job #4: 0.00

Job #WINT3 - External

COMPLAINT: WINTERIZE-FW/ CLASS A/ DESTINATION TRAILER/ DEISEL

Due to the winterization process, most refrigerator filters and water filters will need to be replaced. Because of the variability of filters, customers will be responsible for ordering/supplying the replacement filter for your unit at time of dewinterization in the spring.

Because of the number of different filters being used by manufacturers, Tri-Am RV cannot guarantee that we will have the correct filter in stock at time of the appt. Therefore, we recommend that you either pre-order your filters, or bring them with you at your appointment time.

Initial/Date: _____

CORRECTION: WINTERIZE COMPLETE NO LEAKS FOUND AT THIS TIME

Labor

Code	Description	Hours	Rate	Total
SP120140	WINTERIZE FRESH WATER SYSTEM	1.30	175.00	227.50

Parts

Part #	Description	Qty	Price	Total
13-1639	ANTIFREEZE -50	4	5.39	21.56

Subtotal for Job #WINT3: 249.06

Parts Total:	548.04
Labour Total:	577.50
Sublet Total:	0.00
Extras Total:	0.00
Tax Total:	109.74
Estimate Total:	1,235.28



Customer Signature : _____

Date: 29 Oct 2025

