



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26404
Promised Date:
18 NOV 25



Customer #: 91708
MESSER, CHARLES



WO #: 26404 (Appointment Date: 18 NOV 2025 - Time: 11:00am)

Customer: 91708 - MESSER, CHARLES
Address: 340 FANCY WAY
DANDRIDGE, TN
37725

Home Phone: (865) 278-4687

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #: 10869

Stock Desc: (10869) 2024 KZ-RV SPORTSMEN SE

303QBSE

Model: 303QBSE

Serial #: 4EZTU3120R5090607

Chassis #:

Mileage: 0

Key #: 2000

Req'n #:

License #:

Trim:

Purchase Date: 13 JUN 24

Date In: 18 NOV 25

Promise Date: 18 NOV 25

Promise Time: 09:00am

Schedule Date:

Completed:

Warr. Date: 13 JUN 24

Job #WINT2 - External

WINTERIZE-TT/CLASS C

Due to the winterization process, most refrigerator filters and water filters will need to be replaced. Because of the variability of filters, customers will be responsible for ordering/supplying the replacement filter for your unit at time of dewinterization in the spring.

Because of the number of different filters being used by manufacturers, Tri-Am RV cannot guarantee that we will have the correct filter in stock at time of the appt. Therefore, we recommend that you either pre-order your filters, or bring them with you at your appointment time.

Initial/Date: _____

Labor

Job #	Description	Hours	Total
WINT2	WINTERIZE FRESH WATER SYSTEM	0.00	0.00

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #WINT2: 0.00

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

Subtotal for Job #ROOFINS: 0.00

Job #3 - Warranty

COMPLAINT: WHILE CUST WAS TRAVELING ON THE INTERSTATE THE METAL ON THE LOWER PART ON THE UNIT BEHIND THE LP TANKS BLEW OFF. CUST WOULD LIKE TO TURN THIS OVER TO WARRANTY FOR THE REPAIRS

CAUSE: BOTTOM METAL WRAP ON THE FRONT OF THE UNIT SEPARATED FROM THE UNIT WHILE TRAVELING.



CORRECTION: REPLACE LOWER METAL ON FRONT OF UNIT
RESECURE AND RESEAL AREAS
LABOR 2.0

Subtotal for Job #3: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 20 Nov 2025

W/O: 26404
Promised Date: 18 NOV 25



Customer #: 91708
MESSER, CHARLES

