



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 26406 MURPHY, ERIC



Estimate: 26406 (Appointment Date: 19 NOV 2025 - Time: 11:00am)

Customer: 92937 - MURPHY, ERIC
Address: 9280 hwy 11W
MOORESBURG, TN
37811

Home Phone: (330) 390-0308

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #:

Stock Desc: 2020 A THOR FREEDOM ELITE 22FE

Model: 22FE

Serial #: 1FWE3FN2MDC22498

Chassis #:

Mileage: 21504

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 19 NOV 25

Promise Date: 19 NOV 25

Promise Time: 09:00am

Schedule Date:

Completed:

Warr. Date:

Job #WINT2 - External

WINTERIZE-TT/CLASS C

Due to the winterization process, most refrigerator filters and water filters will need to be replaced. Because of the variability of filters, customers will be responsible for ordering/supplying the replacement filter for your unit at time of dewinterization in the spring.

Because of the number of different filters being used by manufacturers, Tri-Am RV cannot guarantee that we will have the correct filter in stock at time of the appt. Therefore, we recommend that you either pre-order your filters, or bring them with you at your appointment time.

Initial/Date: _____

Labor

Code	Description	Hours	Rate	Total
SP120140	WINTERIZE FRESH WATER SYSTEM	1	175.00	175.00

Parts

Part #	Description	Qty	Price	Total
13-1639	ANTIFREEZE -50	3	5.99	17.97

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	8.75	8.75

Subtotal for Job #WINT2: 201.72

Job #1 - External

CS THAT THE HOUSE BATTERIES WILL NOT CHARGE ,BUT THEN STARTS CHARGING THEN DONT

Subtotal for Job #1: 0.00

Job #2 - External

CS THE ALARM IN THE FRIDGE STARTED GOING OFF (FRIDGE WAS RUNNING ON LP) BUT THEN STARTED WORKING ON AND OFF ON LP



Subtotal for Job #2: 0.00

Job #3 - External

CS THAT THE TOUCH PAD IS ACTING FUNNY GOES BLANK THEN COMES BACK ON AND THEN HAS A GLITCHED SCREEN

Subtotal for Job #3: 0.00

Job #4 - External

EXT WARR

Subtotal for Job #4: 0.00

Job #5 - External

QUOTE ON NEW MATTRESS (INSLIDE)

Subtotal for Job #5: 0.00

Job #6 - External

CS THAT THE SLIDE TOPPER FABRIC IS STARTING TO PULL APART

Subtotal for Job #6: 0.00

Parts Total:	17.97
Labour Total:	175.00
Sublet Total:	0.00
Extras Total:	8.75
Tax Total:	19.67
Estimate Total:	221.39

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 22 Nov 2025

