



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 26588 WRIGHT, DANIEL



Estimate: 26588 (Appointment Date: 29 DEC 2025 - Time: 11:00am)

Customer: 93548 - WRIGHT, DANIEL
Address: 11647 WOLLISTON CIRCLE
SWAN POINT, MD

MD
Home Phone: (423) 972-2993

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #:
Stock Desc: 2022 FW CYCLONE
Model:
Serial #: 12345678925487512
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 29 DEC 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - External

CS THAT A WINDOW IN THE SLIDE HAS BROKEN CHECK AND ADVISE PULL WINDOW TO GET TAG TO ORDER WINDOW

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	11.38	11.38

Subtotal for Job #1: 11.38

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION
CHECK CAULKING _____
CHECK SKYLIGHTS _____
CHECK ROOF VENTS _____
CHECK LUBE & ANTENNA _____
CHECK SATELLITE _____
CHECK RUBBER _____

Subtotal for Job #ROOFINS: 0.00

Job #3 - External

CS THAT THE WALL PANEL NEXT TO BROKEN WINDOW IS PULLING AWAY CHECK AND ADVISE

Subtotal for Job #3: 0.00

Job #4 - External

CUST IS LOOKING INTO THE PAPERS FOR EXT WARRANTY

Subtotal for Job #4: 0.00

Job #5 - External

CHECK SLIDES TO SEE IF THEY NEED ADJUSTED
DRIVER SIDE MAIN SLIDE IS GOING IN SIDEWAYS WHEN OPENING



Subtotal for Job #5: 0.00

Job #6 - External

MAIN AWNING NEEDS ADJUSTED IT WILL NOT GO IN ALL THE WAY AS DESIGNED

Subtotal for Job #6: 0.00

Job #7 - External

BOTH FENDER SKIRTS NEED ATTENTION
ONE IS MISSING

Subtotal for Job #7: 0.00

Job #8 - External

CUST STATED THE UNIT HAS A TIRE RECALL

Subtotal for Job #8: 0.00

Job #WINT3 - External

WINTERIZE-FW/ CLASS A/ DESTINATION TRAILER/ DEISEL

Due to the winterization process, most refrigerator filters and water filters will need to be replaced. Because of the variability of filters, customers will be responsible for ordering/supplying the replacement filter for your unit at time of dewinterization in the spring.

Because of the number of different filters being used by manufacturers, Tri-Am RV cannot guarantee that we will have the correct filter in stock at time of the appt. Therefore, we recommend that you either pre-order your filters, or bring them with you at your appointment time.

Initial/Date: _____

Labor

Code	Description	Hours	Rate	Total
SP120140	WINTERIZE FRESH WATER SYSTEM	1.30	175.00	227.50

Parts

Part #	Description	Qty	Price	Total
13-1639	ANTIFREEZE -50	4	5.99	23.96

Subtotal for Job #WINT3: 251.46

Job #WASH - External

WASH UNIT

Subtotal for Job #WASH: 0.00

Parts Total:	23.96
Labour Total:	227.50
Sublet Total:	0.00
Extras Total:	11.38
Tax Total:	25.63
Estimate Total:	288.47

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 13 Jan 2026

