



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

Estimate: 2881 JOSEPH, MICHAEL



Estimate: 2881 (Appointment Date: 13 JUN 2025 - Time: 09:00am)

Customer: 92875 - JOSEPH, MICHAEL
 Address: 1990 KINGSPORT HWY GREENEVILLE
 TN

37745
 Home Phone: 330-697-7903
 Work Phone:
 Author:CLP
 Location: IH
 Invoice #:

Stock #:
 Stock Desc: 2020 TT FOREST RIVER XLR 29QBS
 Model: 29QBS
 Serial #: 5ZT2XLUB2LZ791096
 Chassis #:
 Mileage:
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date:
 Date In: 13 JUN 25
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed:
 Warr. Date:

Job #EST - External

-CUSTOMER IS AWARE THERE IS A \$200.00 ESTIMATE FEE AT TIME OF UNIT DROP OFF.
 IF WORK IS COMPLETED BY TRI-AM, ESTIMATE FEE CAN GO TOWARDS THE INSURED
 DEDUCTABLE OR CAN BE REFUNDED AFTER THE JOB IS COMPLETED.

-CUSTOMER IS TO PROVIDE CLAIM# AND CONTACT FOR INSURANCE BEFORE A WRITTEN
 ESTIMATE WILL BE STARTED.

-INSURANCE WILL CONTACT THE INSURED (NOT TRI-AM) WITH CLAIM APPROVAL OR DENIAL.
 AFTER YOU HAVE BEEN CONTACTED PLEASE CALL TRI-AM WITH AN UPDATE.

-PARTS WILL ONLY BE ORDERED AT CUSTOMER REQUEST AFTER TRI-AM RECEIVES A FULL
 PARTS DEPOSIT. NO PARTS WILL BE ORDERED OR WORK STARTED WITHOUT A DEPOSIT MADE.

SIGNATURE/DATE: _____

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	43.75	43.75
Subtotal for Job #EST:				43.75

Job #1 - External

REPLACE AWNING ROLLER TUBE AND FABRIC

Labor

Code	Description	Hours	Rate	Total
Z990	REPLACE TUBE AND FABRIC	2	175.00	350.00
Subtotal for Job #1:				350.00

Job #2 - External

REPLACE HARDWARE

Labor

Code	Description	Hours	Rate	Total
Z990	REPLACE HARDWARE	2	175.00	350.00
Subtotal for Job #2:				350.00

Job #3 - External

REPLACE EXHAUST VENT PORT

Labor



Code	Description	Hours	Rate	Total
Z990	REPLACE PORT	0.50	175.00	87.50

Subtotal for Job #3: 87.50

Job #4 - External

REMOVE AND INSTALL GARAGE VENT

Labor

Code	Description	Hours	Rate	Total
Z990	RE	0.50	175.00	87.50

Subtotal for Job #4: 87.50

Job #5 - External

REMOVE AND REINSTALL WINDOW

Subtotal for Job #5: 0.00

Job #6 - External

REMOVE AND REINSTALL CLEARANCE LIGHTS

Subtotal for Job #6: 0.00

Job #7 - External

REMOVE AND REINSTALL FRONT BAGGAGE DOOR

Subtotal for Job #7: 0.00

Job #8 - External

REMOVE AND REINSTALL FRONT WINDOW

Subtotal for Job #8: 0.00

Job #9 - External

REMOVE AND REINSTALL SPEAKERS

Subtotal for Job #9: 0.00

Job #10 - External

REMOVE AND REINSTALL TV BACKER

Subtotal for Job #10: 0.00

Job #11 - External

REMOVE AND REINSTALL FRONT CORNER MOLDING

Subtotal for Job #11: 0.00

Job #12 - External

REMOVE AND REINSTALL BOTH ENTRANCE DOORS



Subtotal for Job #12: 0.00

Job #13 - External

REMOVE AND REINSTALL FURNACE EXAUHST PORT

Subtotal for Job #13: 0.00

Job #14 - External

REMOVE AND REINSTALL WATER HEATER PANEL

Subtotal for Job #14: 0.00

Job #15 - External

REMOVE AND REINSTALL OUTSIDE SHOWER

Subtotal for Job #15: 0.00

Job #16 - External

REMOVE AND REINSTALL 110 OUTLETS

Subtotal for Job #16: 0.00

Job #17 - External

REMOVE AND REINSTALL FENDERSKIRT

Subtotal for Job #17: 0.00

Job #18 - External

REMOVE AND REINSTALL J WRAP

Subtotal for Job #18: 0.00

Job #19 - External

REMOVE AND REINSTALL SIDE METAL

Subtotal for Job #19: 0.00

Job #20 - External

REPAIR DAMAGED FRAMING

Subtotal for Job #20: 0.00

Job #21 - External

SUPPLEMENT FOR SHIPPING AND CRATING WILL BE SENT ONCE INVOICES ARE RECEIVED

Subtotal for Job #21: 0.00

Parts Total: 0.00
Labour Total: 875.00
Sublet Total: 0.00
Extras Total: 43.75
Tax Total: 89.58
Estimate Total: 1,008.33

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 13 Jun 2025

