

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2603804
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2TRTB8SB525587
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	048 / 048B
OWNER INFORMATION		ITEM #	TRT28BHS
		DEALER RO #	73008
		CLAIM START DATE	03/09/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	10-11-24-00-000205	Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-03-09 16:11:35 :: Complaint: Slide will not open or close properly. Cause: Dirty seals and debris on slide causing malfunction Correction: Clean, lubricate and adjust.			
	Model#	Dlr Sub Hrs	1.00	Sub Labor Amt \$190.00
	Serial#	Appr Hrs	1.00	Appr Labor Amt \$190.00

Notes

From the photos, I can't decide if this is the same slide as line 2. Can you verify if it is the same or different slide? AK

It is the same slide. This is for the top and bottom seals, they're dirty and causing it to not operate properly.

Authorized for 1.0 hour to repair slide seals to allow slide to operate correctly. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. NVCB. AK

Labor

Line# 2	Operation Code	Operational Description		
	10-11-01-00-000205	Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-03-09 16:13:05 :: Complaint: Vertical wiper seals damaged on both sides on slide exterior Cause: Seals are damaged Correction: Replace slide seals, 20 feet of BAL exact slide wiper seals			
Model#	Dlr Sub Hrs	3.00	Sub Labor Amt	\$570.00
Serial#	Appr Hrs	2.00	Appr Labor Amt	\$380.00

Notes

From the photos, I can't decide if this is the same slide as line 1. Can you verify if it is the same or different slide? AK

It is the same slide. This is for the vertical seals, they are damaged.

Excessive amount requested. Authorized for 2.0 hour to R/R vertical wiper seals that were damaged. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. NVCB. AK

Labor

Line# 3	Operation Code	Operational Description		
	40-196-24-11-001297	Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-03-09 16:14:14 :: Complaint: Living room light switch reversed Cause: Incorrectly wired Correction: Rewire switch			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$95.00

Appr Labor Amt \$95.00

Authorized .50 hour to change wiring for living room light switch to operate appropriately. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. NVCB. AK

Submitted	Labor Amt	\$855.00	Approved	Labor Amt	\$665.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$855.00		Total	\$665.00

I certify that I have performed these repairs consistent with Forest River Policies.

All repairs described have been inspected and are satisfactory.