

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794  
 MYERS RV CENTER INC  
 12024 CENTRAL AVE S.E.  
 ALBUQUERQUE, NM 87123  
 USA

CLAIM STATUS Authorized  
 CLAIM 2508537  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 5ZT3SN4B6TG706092  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 049 / 049A  
 ITEM # SNF39BUNK  
 DEALER RO # 72055  
 CLAIM START DATE 11/21/2025  
 CLAIM END DATE 01/01/1900

Labor rate: \$190.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

**Line# 3**      **Operation Code**      **Operational Description**  
 30-103-24-00-001125      Linoleum - Interior/Flooring/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : ryliefayth@gmail.com, 2025-11-13 13:57:07 :: Found 2 holes in the linoleum in front the couch between and island one hole about the size of a quarter the other a dime / Hole in the flooring living area between couch and island / Recommend patching the 2 spots 27 3/4 x 12 inches

<b>Model#</b>	<b>Dlr Sub Hrs</b>	2.00	<b>Sub Labor Amt</b> \$380.00
<b>Serial#</b>	<b>Appr Hrs</b>	2.00	<b>Appr Labor Amt</b> \$380.00

**Notes**  
 Wrong code was used  
 The time for this repair is agreeable. This repair is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.

### Labor

**Line# 5**      **Operation Code**      **Operational Description**  
 30-101-01-00-001079      Sliding, Pocket Door Track - Interior/Interior Doors/Replace/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : ryliefayth@gmail.com, 2025-11-13 14:26:05 :: Top header plate for barn door from bedroom to bathroom badly damaged / Door fell off rail during transport damaged top header plate / Recommend replacement See photos 3 x 30 1/4 x 3/4 Additional Note : ryliefayth@gmail.com, 2025-11-14 11:56:04 :: Closest code I could find, let me know if there's a better code to use!

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.40	<b>Sub Labor Amt</b> \$76.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.40	<b>Appr Labor Amt</b> \$76.00

**Notes**

### Labor

**Line# 6**      **Operation Code**      **Operational Description**  
 30-100-01-00-001035      Cabinet Door - Interior/Cabinetry/Replace/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : ryliefayth@gmail.com, 2025-11-14 12:17:19 :: Cabinet face in front bathroom damaged / Chip in face trim / Recommend replacement See photos 3 x 27 x 3/4

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.40	<b>Sub Labor Amt</b> \$76.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.00	<b>Appr Labor Amt</b> \$0.00

**Notes**  
 Customer goodwill replace the cabinet door part only no labor.

### Labor

**Line# 10**      **Operation Code**      **Operational Description**  
 60-140-01-00-001565      Lav Faucet - Plumbing/Bathroom (Lavatory) Sink/Replace/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : ryliefayth@gmail.com, 2025-11-14 12:42:29 :: No water pressure to both master bath sinks or

