



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72055
 Promised Date:
 17 APR 26



WO #: 72055
 Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date: 17 APR 26
 Invoice#:
 Author: ADVISOR
 Stock Desc: 9574 2026 SANIBEL
 39BUNK
 Serial#: 706092
 Chassis#: 5ZT3SN4B6TG706092
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 19 JUL 25
 Time In:

Job #1 - Internal

Transferred to RV*72055-2 on 17 JAN 26
 Estimate amount was 0.00
 CHECK IN NEW UNIT

Labor

Job #	Description	Total
1	DIAGNOSIS	N/C
Subtotal for Job #1:		0.00

Job #2 - Warranty

COMPLAINT: Transferred to RV*72055-1 on 18 NOV 25
 Estimate amount was 0.00
 Auto level system not working showing fault all jacks right rear jack does not move at all

CAUSE: Leveling system not working error all jack fault

CORRECTION: Started at the control panel
 Attempted to Manuel level the jacks
 Front jacks and left rear jacks would move up and down the right rear jack would not move
 Went into the basement to the control board switched the left and right rear and ran the jacks up and down
 the left would move but not the right
 Still in the basement I checked all four fuses to make sure they were not blown all fuses were working.
 Switched the left and right back to the proper position
 Retracted all jacks completely
 Went to the right rear jack to manually lower the jack.
 Found right away one of the power sources was not plugged in all the way
 Plugged the jack in went back to the control panel powered it off and on pressed retract then auto level the
 auto level began working and leveled the unit
 Diagnostic and work completed

Labor

Job #	Description	Total
2	LEVELING SYSTEM DIAGNOSE	0.00
Subtotal for Job #2:		0.00

Job #3 - Warranty

COMPLAINT: Transferred to RV*72055-1 on 18 NOV 25

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



Estimate amount was 0.00
Rear grey tank missing handle

CAUSE: Rear grey tank handle missing completely

CORRECTION: Found grey tank handle was missing along with the all thread bolt
In order to replace the handle I had to get a 1/4 x 20 x 1 1/2 bolt cut the head off
Thread the new handle on then thread into the shaft and tighten it so it would not fall off again

Labor

Job #	Description	Total
3	TANK HANDLE	0.00

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: Found 2 holes in the linoleum in front the couch between and island one hole about the size of a quarter the other a dime

CAUSE: Hole in the flooring living area between couch and island

CORRECTION: Recommend full replacement of flooring in kitchen living area
Total size 9 x 18
Or patching the 2 spots 27 3/4 x 12 inches
Forest river sent the wrong Lino
Hold for parts

Labor

Job #	Description	Total
4	LINOLEUM	30.40

Parts

Part #	Description	Qty	Price	Total
F100727420	LINOLEUM, 102" DESIGNER CAREFREE	3.00	12.98	38.94

Sublet

Description	Total
REPAIR LINOLEUM	349.60

Other Services

Code	Description	Qty	Price	Total
FRT	CRATE	1.00	5.00	5.00
FRT	SHIPPING & HANDLING CHARGES	1.00	205.16	205.16

Subtotal for Job #4: 629.10

Job #5 - Warranty

COMPLAINT: Transferred to RV*72055-1 on 18 NOV 25
Estimate amount was 0.00
Trim coming off the wall/baseboard behind barn door to bedroom from living room

CAUSE: Trim came loose

CORRECTION: Stapled trim back to the wall and filled the new staple hole with putty
Work completed

Labor

Job #	Description	Total
5	TRIM	0.00

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: Top header plate for barn door from bedroom to bathroom badly damaged

W/O: 72055
Promised Date: 17 APR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,





CAUSE: Door fell off rail during transport damaged top header plate

CORRECTION: Recommend replacement

See photos

3 x 30 1/4 x 3/4

Found the stile with the door latch on the left was not in the correct position was off center to the left leaving a gap on the bathroom side exposing cut end of he paneling.

Removed the top stile and the stile on the left

Cut new stile from the new piece sent.

Recentered the stile on the latch side to be even top to bottom and nailed it back in place.

Installed the top stile and nailed it in place

Used putty to fill all nail holes.

Resecured top batten strip inside the bathroom

Resecured the batten to the left side stile bedroom side

Work completed

Labor

Job #	Description	Total
6	STILE	76.00

Parts

Part #	Description	Qty	Price	Total
F100743506	STILE, ANDOVER MALT 18MM 3" X 108"	1.00	11.90	11.90

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	205.16	205.16

Subtotal for Job #6: 293.06

Job #7 - Warranty

COMPLAINT: Cabinet face in front bathroom damaged

CAUSE: Chip in face trim

CORRECTION: Recommend replacement

See photos

3 x 27 x 3/4

To access the stile in the middle of the cabinet

The bottom panel which is stapled from the inside had to be removed

Shelf panel was then removed

Behind the stile to access the screws hold it in place the trim on the top that holds the base panel in place had to be removed

The whole shelf support had to be removed by pulling staples and removing 5 screws

The right cabinet door had to be removed

The stile was then removed by taking the 4 side screws out

A new piece was cut to fit

New set in place and attached the the cabinet face

The shelf supports were nailed and screwed back in place

The base panel was stapled back in place from the inside

The shelf was stapled back down

All visible staple and nail holes were puttied

The cabinet door was reattached

Work completed

Labor

Job #	Description	Total
7	CABINET	76.00

Parts

Part #	Description	Qty	Price	Total
F100684215	STILE, ANDOVER MALT 18MM X 1-1/2" X 108"	1.00	7.71	7.71



Subtotal for Job #7: 83.71

Job #8 - Warranty

COMPLAINT: Transferred to RV*72055-1 on 18 NOV 25
Estimate amount was 0.00
Seam tape above main living room slide coming off the wall

CAUSE: Bubbled and coming off the wall

CORRECTION: Smoothed the seal out and pushed it back under the crown molding
Work completed

Labor

Job #	Description	Total
8	SEAM TAPE	0.00

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: Transferred to RV*72055-1 on 18 NOV 25
Estimate amount was 0.00
Batten trim left side of barn door from living room to bedroom coming off the wall

CAUSE: Trim came loose from the wall

CORRECTION: Stapled the trim back to the wall and puttied the new staple holes work completed

Labor

Job #	Description	Total
9	TRIM	0.00

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: Transferred to RV*72055-1 on 18 NOV 25
Estimate amount was 0.00
Left master bath sink leaking

CAUSE: Water leak left Master bath facet

CORRECTION: Found the facet was misaligned with the cut out in the counter top allowing water to run between the facet and the counter top when water splashed around the base of the facet.
Checked all plumbing connections and they were not leaking
Opened the cabinet door with a flat blade screw driver loosened the mounting screws for the facet aligned the facet to the center of the hole closing the gap found at the front of the facet and tightened mounting screws
No gap and no leaking
Work completed

Labor

Job #	Description	Total
10	BATHROOM WATER LEAK	0.00

Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: No water pressure to both master bath sinks or toilet in master bathroom, on city water and pump

CAUSE: Low water pressure in both master bath sinks and toilet
Both facets full of saw dust

CORRECTION: Found there to be no water pressure in both sinks and toilet
Took the sink facet apart and it to be full of saw dust and white foam

W/O: 72055
Promised Date: 17 APR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,





Attempted to clean the facet by running water through it with the facet apart and using high pressure air facets are still clogged
 Recommend full replacement of both facets see attached pictures
 Found the toilet had no water pressure
 Removed the flush valve and it to be completely full of saw dust
 Was able to clean the debris out of the valve using a dental pick and high pressure air toilet now has correct water pressure
 Hold for approval and parts
 Removed left facet found the locking nut was so tight the whole base of the facet came off, had to use two set of Pillars to break the nut loose to get the facet out of the counter top.
 Centered and reinstalled new facet reconnected water lines
 Removed right facet
 Installed new facet and connected water lines
 Job completed
 Old facets turned into Brian

Labor		
Job #	Description	Total
11	WATER SYSTEM TROUBLESHOOT	190.00

Parts				
Part #	Description	Qty	Price	Total
F100811573	LIPPERT FLOMAX WATERFALL LAV FAUCET - MATTE BLACK	2.00	187.77	375.54

Other Services				
Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	17.75	17.75

Subtotal for Job #11: 583.29

Job #12 - Warranty

COMPLAINT: Transferred to RV*72055-1 on 18 NOV 25
 Estimate amount was 0.00
 Kitchen sink leaking

CAUSE: Disconnected water line

CORRECTION: Found when water system was pressurized the hot water line under the kitchen sink was not connected
 Flooded the kitchen before the water pump could be shut off
 Connected the water line and tested under pressure both pump and city water not leaking
 Work completed

Labor		
Job #	Description	Total
12	KITCHEN SINK	0.00

Subtotal for Job #12: 0.00

Job #13 - Warranty

COMPLAINT: Transferred to RV*72055-1 on 18 NOV 25
 Estimate amount was 0.00
 Bottom bunk in front room far right large gouges in the wall

CAUSE: Several large gouges in panel lower bunk bed far right side

CORRECTION: Was able to use a putty filler stick and fill the gouges
 Work complete

Labor		
Job #	Description	Total
13	REPAIR PANEL	0.00



Subtotal for Job #13: 0.00

Job #14 - Warranty

COMPLAINT: Transferred to RV*72055-1 on 18 NOV 25
Estimate amount was 0.00
Failed LP drop test twice

CAUSE: Failed drop test twice

CORRECTION: Started at the tanks bubble tested each connection under the unit, when I got to the quick disconnect in the rear of the unit and found the valve was open and there was some debris in the connector allowing gas to leak slightly
Cleaned out the disconnect turned the valve off
Retested the unit and drop test was completed without any leaks
Work completed

Labor

Job #	Description	Total
14	LP SYSTEM DIAGNOSTIC TIME	0.00

Subtotal for Job #14: 0.00

Job #PDI1 - Internal

Transferred to RV*72055-2 on 17 JAN 26
Estimate amount was 0.00
PRE-PDI NEW TT - 3.0

Labor

Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #PDI1: 0.00

Job #WIN-DLX - Internal

Transferred to RV*72055-2 on 17 JAN 26
Estimate amount was 0.00
WINTERIZE INCLUDE W/D, ICEMAKER

Labor

Job #	Description	Total
WIN-DLX	WINTERIZE RV - DELUXE CLASS A	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WIN-DLX: 0.00

Parts Total:	434.09
Labour Total:	372.40
Sublet Total:	349.60
Extras Total:	433.07
WORK ORDER TOTAL:	1,589.16

W/O: 72055
Promised Date: 17 APR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 17 Apr 2026

Customer Signature : _____

Customer Work Order

W/O: 72055
Promised Date: 17 APR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,

