

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0008794	<b>CLAIM STATUS</b>	Authorized
MYERS RV CENTER INC		<b>CLAIM</b>	2607854
12024 CENTRAL AVE S.E.		<b>CLAIM ORIGIN</b>	WEB
ALBUQUERQUE, NM 87123		<b>ORIGINAL CLAIM ID</b>	
USA		<b>VIN</b>	5ZT2AVRB5TB940745
		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$190.00	<b>SITE/WAREHOUSE</b>	050 / 050
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	AVT26DBS
LARRY OTHEL KLUMPP		<b>DEALER RO #</b>	72981
35 DALTON		<b>CLAIM START DATE</b>	03/12/2026
Moriarty, NM 87035		<b>CLAIM END DATE</b>	01/01/1900
USA			
<b>Retail Date of Purchase</b>	06/26/2025	<b>WARRANTY EXPIRATION DATE</b>	06/26/2026

## Claim Line Details

### Labor

<b>Line#</b>	<b>Operation Code</b>	<b>Operational Description</b>		
1	20-58-12-00-000610	Exterior Molding for Aluminum Siding - Exterior/Metal, Aluminum Siding/ Resecure or Tighten/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : stephanie@dealer-advisors.com, 2026-03-12 14:40:14 :: Complaint: Front metal panel is loose Cause: Stripped screws and missing screws Correction: Replaced missing screws and remove and replace the stripped ones with longer thicker screws and metal is now secure.			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.30	<b>Sub Labor Amt</b>	\$57.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b>	\$57.00
	<b>Notes</b>			
	NVCB .30 to R&R the stripped out screws and secure the loose ones. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.			

<b>Submitted</b>	Labor Amt	\$57.00	<b>Approved</b>	Labor Amt	\$57.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$57.00		Total	\$57.00

**DEALER** \_\_\_\_\_ **DATE** \_\_\_\_\_

**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

**CUSTOMER** \_\_\_\_\_ **DATE** \_\_\_\_\_

**SIGNATURE**

All repairs described have been inspected and are satisfactory.