

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2550448
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	4X4TUMB22TB035570
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	080 / 080B
OWNER INFORMATION		ITEM #	UMT26BH-80
		DEALER RO #	72475
		CLAIM START DATE	01/14/2026
		CLAIM END DATE	03/12/2026
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor				
Line# 1	Operation Code	Operational Description		
	20-46-01-00-000721	Window - Exterior/Windows/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-14 10:41:31 :: Complaint: Front window broken at delivery, noted on DAF Cause: Front window was broken at delivery Correction: Remove and replace window			
Model#	Dir Sub Hrs	2.00	Sub Labor Amt	\$380.00
Serial#	Appr Hrs	1.00	Appr Labor Amt	\$190.00
	Notes			
	Excessive time requested. Time reduced based on photos, description, and flat rate code.			

Line# 1	Item #		Description			
	F100397091		224-FR BLACK WINDOW BULB SEAL W/PSA SOLD BY THE LF			
	Model #		Serial #		Part tag	
	Sub Qty	15.00	Sub Dlr Price	\$4.55	Sub Freight	\$0.00
	Appr Qty	15.00	Appr Dlr Price	\$4.55	Appr Freight	\$0.00
	Notes					
Line# 2	Item #		Description			
	F100737541		56.63 X 29.63-90D 5MM RPOD UNMAPPED 2026 FRONT WINDOW **2025003146**			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$539.33	Sub Freight	\$199.51
	Appr Qty	1.00	Appr Dlr Price	\$539.33	Appr Freight	\$199.51
	Notes					

Line# 3	Operation Code 30-102-24-00-003061	Operational Description Ceiling Panel - Touchup - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code		
	Complaint, Cause, Correction Original Note : stephanie@dealer-advisors.com, 2026-01-14 10:44:09 :: Complaint: There are stains on the ceiling Cause: Stains on the ceiling in bedroom and living room Correction: Cleaned the stains			
Model#	Dir Sub Hrs	0.10	Sub Labor Amt	\$19.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00
Notes				

Labor

Line# 4	Operation Code	Operational Description		
	40-106-01-12-001216	Clearance Light - Electrical/12 Volt Exterior/Replace/Exterior Lighting		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-14 10:45:21 :: Complaint: Right rear marker light is not working Cause: Top right marker light is damaged, wire is pulled out Correction: Remove and replace light			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$38.00	
Notes				

Part					
Line# 1	Item #	Description			
	20X29076A	3/4" LED CLEARANCE LIGHT - RED *321812*			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$4.84	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$4.84	Appr Freight \$0.00
Notes					

Labor					
Line# 5	Operation Code		Operational Description		
	30-98-01-00-000989		Inter-Spring Mattress - any size - Interior/Beds, Mattress/Replace/No Tread Code		
	Complaint, Cause, Correction				
	Original Note : stephanie@dealer-advisors.com, 2026-01-14 10:46:40 :: Complaint: Mattress has glass all over it from the window breaking Cause: Window broke Correction: Replace mattress				
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00	
Notes					
Please provide pictures					
Photo added					

Part					
Line# 1	Item #	Description			
	F100681857	MATTRESS, EVERREST 66 X 80 - SEA WAVE GREY			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$120.04	Sub Freight \$100.00
	Appr Qty	1.00	Appr Dlr Price	\$120.04	Appr Freight \$100.00
Notes					

Labor					
Line# 6	Operation Code		Operational Description		
	20-43-01-00-000589		Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code		
	Complaint, Cause, Correction				
	Original Note : stephanie@dealer-advisors.com, 2026-01-14 10:47:58 :: Complaint: Related to line 1, window broke and decals need to be replaced Cause: Window broken Correction: Install decal in front window of coach				
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$95.00		
Serial#	Appr Hrs	0.50	Appr Labor Amt \$95.00		
Notes					
Please provide pictures					
The window is shattered, photos for the window were attached to job 1. This is in relation to that.					

Part					
Line# 1	Item #	Description			
	F100770271	DECAL, #1 FRT DIG UNMAPPED LOGO **UM2651433-01**			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$16.96	Sub Freight \$44.25
	Appr Qty	1.00	Appr Dlr Price	\$16.96	Appr Freight \$44.25
Notes					

Submitted	Labor Amt	\$570.00
	Parts & Freight	\$1,029.48
	Total	\$1,599.48

Approved	Labor Amt	\$380.00
	Parts & Freight	\$1,029.48
	Total	\$1,409.48

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	