



Warranty Authorization Form

Date: 4/10/2026

General Information

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200
cbruce@americanrvcenter.com

Pre-Auth #: 121791 Unit: 7M5TD3126TC307285
Series: Delta Model: 2026DEL281BH
Notes: 3/31 Conner - put back into pending so dealership can add lines.
Status: Approved with Modifications

Dealer Information

American RV
(812) 867-5200
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 14078 SLIDEOUT FASCIA - INTERIOR - REPLACE

Fault Code: DAMAGED

Serial #:

Model #:

Notes:

Problem: SCRATCH ON TRIM IN SLIDE ROOM ABOVE RECLYNER ON TOP LEFT SIDE WHEN STANDING IN FRONT OF RECLYNER

Time Requested: .6

Cause: Retrieved unit and hooked up Shore power. Compartment was locked with disconnect... pulled door cylinder and retrieved Key for Compartment and turned disconnect ON. Took pics and submitted part request for Facia Board with chips in it. Turned disconnect back off, disconnect Shore power and put back into storage.

Time Allowed: .6

Sublet Repairs: 0.00

Remedy: need to replace the slide facia

Part Return Req: No

Status: Approved

Operation Line 2

Flat Rate Code: 14061A LINO - REPAIR (Please provide length and wide of area)

Fault Code: Lino - Main Floor

Serial #:

Model #:

Notes: 4/1/26- SP- PLEASE OBTAIN A SUBLET FOR LINO REPAIR.
4/1/26 BH SUBLET ADDED FOR LINO REPAIR

Problem: WHEN CUSTOMER RAN THE SLIDE ROOM OUT IT TORE A SPOT IN THE FLOOR

Time Requested: 0

Cause: Found and took pics of cut on vynle floor.

Time Allowed: 0

Remedy: MIGHT HAVE TO SUBLET OUT IF APPROVED

Sublet Repairs: 425.00

Part Return Req: No

Status: Approved

Operation Line 3

Flat Rate Code: 14020 CABINET - DRAWER FRONT - REPAIR
(Photos required)

Fault Code: POOR CONNECTION

Serial #:

Model #:

Notes:

Problem: MAGNET AND SCREW HAS COME OFF OF THE BOTTOM DRAWER

Time Requested: .15

Cause: Remount Magnet for internal drawer.

Time Allowed: .1

Remedy: Located the drawer customer was talking about after hunting thru the unit... turned out the drawer was Located inside and behind Cabinet Doors under TV. Remounted Magnetic catch.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved with Modifications

Operation Line 4

Flat Rate Code: 22308 ENTRANCE DOOR - SCREEN DOOR - REPAIR
(photos of defect and door tag)

Fault Code: TORN / PUNCTURED

Serial #:

Model #:

Notes:

Problem: SCREEN IN DOOR BY BUNK HAS HOLE IN THE SCREEN

Time Requested: .8

Cause: Damaged screen

Time Allowed: .8

Remedy: Took pics, measured and cut new piece of screen. Removed old screening from damaged section of door. One single insert that holds the screening in is installed on whole door including top and bottom section... i had to center the new screening and work from the top middle down each side which was difficult to keep screen tight while keeping slack out of insert while also forcing insert into track but i managed and cut extra off.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved

Operation Line 5

Flat Rate Code: 14045B DINETTE TABLE - REPLACE (Photos required)

Fault Code: CHIPPED

Serial #:

Model #:

Notes:

Problem: TABLE HAS CHIP IN THE CORNER.

Time Requested: .3

Cause: Took pics and measurements, 29in x 32in x 1in and submitted part request.

Time Allowed: .3

Remedy: REMOVE AND REPLACE

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved

Operation Line 6

Flat Rate Code: 14007 BLIND - ADJUST

Fault Code: MISALIGNED

Serial #:

Model #:

Notes:

Problem: BLIND BEHIND RIGHT SIDE OF COUCH IS CROOKED

Time Requested: .3

Cause: Blind mount brackets were pulled from their mounted positions

Time Allowed: .1

Remedy: The lock mounted brackets that secures blinds in place was onky being held up by the center mount... both of the end mounts were pulled from the blind covers where they mount. Had to drop the blind and unclip the brackets off of blind and reinstall them and reinstall blind.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved with Modifications