

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2650234
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CXNB0TS049693
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	220 / 220A
		ITEM #	APTT242BARV
		DEALER RO #	79639
		CLAIM START DATE	04/22/2026
		CLAIM END DATE	01/01/1900
Labor rate:	\$195.00		
OWNER INFORMATION			
DAVID L GOEBEL			
1644 E AUTUMN RIDGE			
Haubstadt, IN 47639			
USA			
Retail Date of Purchase	03/28/2026	WARRANTY EXPIRATION DATE	03/28/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	40-196-24-11-001297	Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-04-22 10:03:22 :: ONE OF THE LIGHTS OVER THE BED IS NOT WORKING Light not working. Brought unit in. Connected to shore power and ran out slideroom to access bedroom. Went to bedroom and saw light wasnt working. Remoced cover and sxrews from light. Saw quick connect on positive wires. Wires had loose connection. Used crimp to put wires together and made a good connection to power light on. Placed light back up and screwed inonplace after putting wires back up channel. Placed cover on light. Light now works.			
	Model#	Dlr Sub Hrs	0.25	Sub Labor Amt \$48.75
	Serial#	Appr Hrs	0.25	Appr Labor Amt \$48.75
	Notes			
	redo wire connections			

Labor

Line# 2	Operation Code	Operational Description		
	60-136-15-00-001499	Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-04-22 10:04:05 :: WHEN FLUSHING THE BLACK TANK IT WAS FILLING THE UNDERBELLY AND LEAKING IN THE UNIT Black tank flush Brought unit in. Connected to black tank flush and ran water through it. While running went inside and saw line had been split and was leaking water all under shower leaking into under belly. Cut off line that was cut. Added cupplers on both sides of line and place new line in. Crimped new line in place with cuppler and ran water through line. And no leaks found. Closed shower back up after drying			
	Model#	Dlr Sub Hrs	0.60	Sub Labor Amt \$117.00
	Serial#	Appr Hrs	0.50	Appr Labor Amt \$97.50
	Notes			
	cut out bad water line and install sectionof water line			

Submitted	Labor Amt	\$165.75	Approved	Labor Amt	\$146.25
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$165.75		Total	\$146.25

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.