



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79143
Promised Date:
06 MAR 26

CUSTOMER WORK ORDER

WO #: 79143

Customer: 56540 - FISCHER, SARAH -
812-550-5670

Tag:

Author: BH

Location: 0427 CHECK WORK

Stock #: 11559

Stock Desc: 2025 TT COACHMEN
FREEDOM EXPRESS 21SE

Chassis #: 5ZT2FEKB7SW030811

Serial #: 5ZT2FEKB7SW030811

Mileage:

Licence:

Invoice #:

Date In: 02 MAR 26

Promised: 06 MAR 26

Date Sched:

Completed: 25 APR 26

Warr. Date: 06 MAR 26

Job #FPDINTT - Internal

COMPLAINT: Transferred to BAS*79448 on 01 APR 26

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly installed new battery air correct in all 5 tires. Exterior inspection awning fabric and hardware looks and works properly Awning lights work properly. Seale up front amber light with clear silicone and back of slideroom with clear silicone. Exterior inspection looks good now. Roof inspection found a small void in the sealer that I filled with dicor self-leveling. Roof good now. Hooked to city water and flushed out all the lines. Stove works properly microwave works properly both refrigerators work properly furnace works properly water heater works properly. Tv antenna works properly now that i took the 90 degree cable connector off. All the windows work properly and all the blinds except the table one has a rip in it that i put a parts request in for. Put water in fresh tank and flushed out all the lines with the water pump. Water pump works properly

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Subtotal for Job #FPDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: Transferred to BAS*79448 on 01 APR 26

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Turn valve to winterize and pumped winterize solution through the pump to bathroom shower cold and hot until solution was there then repeated for bathroom faucet toilet kitchen faucet and outside kitchen. Then depressed city water inlet. Drained black tank and gray tank and fresh tank and Drained water heater. Used 2 gallons

Labor



Customer #: 56540
FISCHER, SARAH

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JTW	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #CAMERA - Internal

COMPLAINT: Transferred to BAS*79448 on 01 APR 26

Estimate amount was 0.00

INSTALL WIRELESS CAMERA

CAUSE: Install camera

CORRECTION: Took middle light off and had to drill a hole in the exterior wall of this unit because it wasn't prepped for a rear camera. And fish the camera wires up to the light hole and connected them to the wires from the light. And tested the camera and it works properly. Put budle tape on the back of the mounting bracket and sealed up with clear silicone. And reinstalled the running light. Good to go

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #CAMERA: 0.00

Job #SWAP - Internal

COMPLAINT: Transferred to BAS*79448 on 01 APR 26

Estimate amount was 0.00

SWAP CUSTOMER'S HITCHWORK

CAUSE: Swapped hitch setup

CORRECTION: Unbolted the L brackets from the trade. Bolted the L brackets onto the new camper. Leveled the camper then matched the truck hitch. Connected the truck to the camper. Adjusted as necessary. Tightened all hardware. Connected the 7-way plug, safety chains and breakaway cable and coupler.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #SWAP: 0.00

Job #1 - Warranty

COMPLAINT: REAR RED SIDE MARKER LIGHT NOT WORKING

CAUSE: Right rear light doesn't work

CORRECTION: Took light off and the wires was on the wrong wires. So i tested witch wire was power and negative and wired them up correctly and it works properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	11.10
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	7.40

W/O: 79143
Promised Date: 06 MAR 26

Customer #: 56540
FISCHER, SARAH

Subtotal for Job #1: 18.50

Job #2 - Warranty

COMPLAINT: FRONT AMBER MARKER LIGHT NOT WORKING

CAUSE: Front left amber running light doesn't work

CORRECTION: Took light off and tested it i had power there but light doesn't work so i got a new light and installed it and wired it up and new light works properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	7.40
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	29.60

Parts

Part #	Description	Qty	Price	Total
11073	LIGHT, CLEARANCE AMBER SURFACE MOUNT	1.00	2.25	2.25

Subtotal for Job #2: 39.25

Job #3 - Warranty

COMPLAINT: OUTSIDE HOT WATER CONNECTER THAT RUNS TO THE FAUCET HAS A CRACK IN IT

CAUSE: Outdoor kitchen water line leaking

CORRECTION: On inspection of the outside kitchen noticed a leak at the connection. Try a new cone washer it didnt fix it so then i installed a new connector and got it crimped on and no leak. All good now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	46.25

Parts

Part #	Description	Qty	Price	Total
681487	1/2" BARB X 1/2 FPT SWIVEL CONE	1.00	2.24	2.24
10-7150	CONE WASHER SWIVEL SEAL	1.00	0.26	0.26

Subtotal for Job #3: 48.75

Job #4 - Warranty

WINDOW BLIND IS DAMAGED

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	31.45
Z990	MISC LABOUR CODE (EXTERNAL)	BB	5.55

Parts

Part #	Description	Qty	Price	Total
F100204161	SHADE, NIGHT 50X32 BLACK PLEATED IMP	1.00	32.86	32.86

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	42.37	42.37

Subtotal for Job #4: 112.23

Job #5 - Warranty

COMPLAINT: WATER HEATER DOOR IS RUSTED.

CAUSE: Water heater door has rest on it



CORRECTION: I took the rusty door off and replaced it with a new one. I put budle tape on the back of the door and new screws and sealed the outside with clear silicone.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50

Parts

Part #	Description	Qty	Price	Total
07-7912	6285AEB BLK DEMAND WH DOOR - SUBURBAN	1.00	60.78	60.78

Subtotal for Job #5: 116.28

Parts Total: 98.39
Labour Total: 194.25
Sublet Total: 0.00
Extras Total: 42.37
WORK ORDER TOTAL: 335.01

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 25 Apr 2026

W/O: 79143
Promised Date: 06 MAR 26



Customer #: 56540
FISCHER, SARAH

