



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26937



WO #: 26937 (Appointment Date: 06 APR 2026 - Time: 03:00pm)

Customer: 52115 - RICE, TARA L.
 Address: 1900 MEADOW SPRING CT
 RUSSELLVILLE, TN
 37860

Home Phone: (423) 312-3059

Work Phone:
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 367BH
 Stock Desc: 2024 FW FOREST RIVER CHAPERAL
 Model: 367BH
 Serial #: 5ZT3CH2B1RA331015
 Chassis #:
 Mileage:
 Key #:
 Req'n #:
 License #:
 Trim: 367BH

Purchase Date:
 Date In: 06 APR 26
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed:
 Warr. Date:

Job #1 - External

COMPLAINT: CUST CALLED AND STATED HIS TANKLESS WATER HEATER IS THROWING A E5 CODE. AT DROP OFF HE STATED THE FAN IS NOT SPINNING ON THE WATER HEATER. CHECK AND ADVISE

CAUSE: WATER HEATER BOARD SMELLS BURNT AND MELTED SPOT ON BOARD NEXT TO FAN PLUG

CORRECTION: REPLACE BOARD
 LABOR AND DIAG 1.0

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00
Subtotal for Job #1:				0.00

Job #2 - Warranty

COMPLAINT: FRIDGE IS MAKING A NOISE AT RANDOM TIMES. SOUNDS LIKE A DIESEL TRUCK, CUST SENT VIDEO TO ALLOW TECH TO SEE WHAT HE IS HEARING WHEN USING THE UNIT.

CAUSE: CONFIRMED FRIDGE IS MAKING A RATTLE NOISE INTERNALLY AT RANDOM TIMES WHEN RUNNING

CORRECTION: COMPRESSOR IS NOT WORKING AS DESIGNED
 REPLACE FRIDGE
 LABOR AND DIAG 2.5

Subtotal for Job #2: 0.00

Parts Total: 0.00
 Labour Total: 0.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 0.00

Customer #: 52115
 RICE, TARA L.



I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 24 Apr 2026

Customer Signature : _____

W/O: 26937

Customer Work
Order



Customer #: 52115
RICE, TARA L.

