

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79152
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11727 - 2026 COUGAR 320RDS 4YDFCGR2XT2505130
VIN: 4YDFCGR2XT2505130 HIN: SER#: 4YDFCGR2XT2505130
Mileage: 0 Work Order Comp: 23 MAR 26
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 02 MAR 26 Inv #: 427718

WO # Job # Description JOB INFORMATION

79152 1 REGULATOR MAXES OUT AT 10
Lp regulator
During the pdi was running the lp drop test and the lp regulator
wouldn't go above 10 wc. Lp regulator didn't make a sound. Got a
new lp regulator. Shut off the lp the disconnect thelp tank on
the off doorside. Disconnected the lp lines from the lp
regulator. Put pipe thread sealer on the lp hoses and connected
to the new lp regulator. Tested the new lp regulator and it made
noise of flow. The manometer was reading correctly.

79152 2 SCRATCH ON TV LID
Scratch
Took pictures and put in a parts request for a new tv cover

79152 3 BATHROOM FLOOR TRIM HAS STRECH MARKS
Damaged trim
Took pictures and put in parts request for new trim

79152 6 DENT ON LOWER FIBERGLASS
Dent
Took pictures of the dent then put in a parts request for new
sheet of metal or fiberglass.

79152 4 BIG SLIDEROOM FACIA TRIM IS WARPED
fascia trim
Stapled the trim then covered with filler.

Claim : 79152

```
*****
WO #      Job #   Description      JOB INFORMATION
*****
```

```
79152      5      OFF DOOR SIDE CAP IS MISSING SEALANT
           No silicone
           Took pictures of the cap corner trim with no silicone and applied
           silicone to fill the void.
```

```
*****
Part No   Job#   Description      PARTS      Qty      Price      Total
*****
```

Part No	Job#	Description	PARTS	Qty	Price	Total
MECMEGR-253HP	1	MEGR-253HP LP REGULATOR	2-STAGE H	1.00	78.96	78.96
765818	2	Countertop - TV Lid - 5/8" x 9 1/2"		1.00	65.81	65.81
766854	3	Trim - ISC - .305" x .66" x 96" -		1.00	3.04	3.04
763309	6	Cover - Bulkhead/Pin Box - .100"		1.00	187.89	187.89
SIK432053	6	CLEAR SIKASIL PLUS		1.00	11.08	11.08

```
*****
Lab Code  Job#   Description      LABOUR      Hrs      Rate      Total
*****
```

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISCELLANEOUS REPAIR		0.50	180.00	90.00
Z990	2	MISCELLANEOUS REPAIR		0.10	180.00	18.00
Z990	2	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	3	MISCELLANEOUS REPAIR		0.14	180.00	25.20
Z990	3	MISCELLANEOUS REPAIR		0.06	180.00	10.80
Z990	6	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	6	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	6	MISCELLANEOUS REPAIR		4.00	180.00	720.00
Z990	4	MISCELLANEOUS REPAIR		0.10	180.00	18.00
Z990	4	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	5	MISCELLANEOUS REPAIR		0.20	180.00	36.00

```
*****
Excode    Job#   Description      EXTRAS      Qty      Price      Total
*****
```

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	2	FREIGHT - TV LID AND ISC TRIM		1.00	77.43	77.43
FRT	6	FREIGHT - BULKHEAD		1.00	198.27	198.27

```
Parts Total:      346.78
Labour Total:     918.00
Sublet Total:      0.00
Extras Total:     275.70
```

>>>> Claim Total: 1,540.48

Customer Signature: _____

Date: _____