

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2508537
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT3SN4B6TG706092
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	049 / 049A
OWNER INFORMATION		ITEM #	SNF39BUNK
		DEALER RO #	72055
		CLAIM START DATE	11/21/2025
		CLAIM END DATE	04/23/2026
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor

Line# 3	Operation Code		Operational Description	
	30-103-24-00-001125		Linoleum - Interior/Flooring/Repair/No Tread Code	
	Complaint, Cause, Correction			
	Original Note : ryliefayth@gmail.com, 2025-11-13 13:57:07 :: Found 2 holes in the linoleum in front the couch between and island one hole about the size of a quarter the other a dime / Hole in the flooring living area between couch and island / Recommend patching the 2 spots 27 3/4 x 12 inches			
	Model#	Dir Sub Hrs	2.00	Sub Labor Amt \$380.00
Serial#	Appr Hrs	2.00	Appr Labor Amt \$380.00	
	Notes			
	Wrong code was used			
	The time for this repair is agreeable. This repair is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.			

Line# 1	Item #	Description			
	F100727420	LINOLEUM, 102", DESIGNER CAREFREE, BERLIN STONEY GROUND, CC292, 29602922085			
	Model #	Serial #	Part tag		
	Sub Qty 3.00	Sub Dlr Price \$44.63	Sub Freight	\$54.47	
	Appr Qty 3.00	Appr Dlr Price \$38.95	Appr Freight	\$54.05	
	Notes				
	Dealer has submitted a part cost different than what was charged on the Forest River parts order, S5473469. The approved cost has been adjusted to \$11.29 + state allowed mark-up of 15%.				

Labor

Line# 5	Operation Code		Operational Description	
	30-101-01-00-001079		Sliding, Pocket Door Track - Interior/Interior Doors/Replace/No Tread Code	
	Complaint, Cause, Correction			
	Original Note : ryliefayth@gmail.com, 2025-11-13 14:26:05 :: Top header plate for barn door from bedroom to bathroom badly damaged / Door fell off rail during transport damaged top header plate / Recommend replacement See photos 3 x 30 1/4 x 3/4 Additional Note : ryliefayth@gmail.com, 2025-11-14 11:56:04 :: Closest code I could find, let me know if there's a better code to use!			
	Model#	Dlr Sub Hrs	0.40	Sub Labor Amt \$76.00
Serial#	Appr Hrs	0.40	Appr Labor Amt \$76.00	
Notes				

Line# 1	Item #	Description
	F100743506	STILE, MM, LVL SE, 18MM X 3 X 108, ANDOVER MALT, 47094016
	Model #	Serial # Part tag

Sub Qty	1.00	Sub Dlr Price	\$11.90	Sub Freight	\$210.16
Appr Qty	1.00	Appr Dlr Price	\$11.90	Appr Freight	\$210.16

Notes

Line# 2	Item #	Description				
	USERPART	Putty & nails				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$3.80	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$3.80	Appr Freight	\$0.00

Notes

Labor

Line# 6	Operation Code	Operational Description			
	30-100-01-00-001035	Cabinet Door - Interior/Cabinetry/Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : ryliefayth@gmail.com, 2025-11-14 12:17:19 :: Cabinet face in front bathroom damaged / Chip in face trim / Recommend replacement See photos 3 x 27 x 3/4				
	Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$76.00
Serial#	Appr Hrs	0.00	Appr Labor Amt	\$0.00	

Notes

Customer goodwill replace the cabinet door part only no labor.

Part

Line# 1	Item #	Description				
	F100684215	STILE, MM VC LVL SE, 18MM X 1-1/2 X 108, ANDOVER MALT, 47092114				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$8.08	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$7.71	Appr Freight	\$0.00

Notes

Dealer has submitted a part cost different than what was charged on the Forest River parts order, S5370830. The approved cost has been adjusted to \$6.70 + state allowed mark-up of 15%.

Line# 2	Item #	Description				
	USERPART	Putty, staples, nails				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$3.80	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$3.80	Appr Freight	\$0.00

Notes

Labor

Line# 10	Operation Code	Operational Description			
	60-140-01-00-001565	Lav Faucet - Plumbing/Bathroom (Lavatory) Sink/Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : ryliefayth@gmail.com, 2025-11-14 12:42:29 :: No water pressure to both master bath sinks or toilet in master bathroom, on city water and pump / I water pressure in both master bath sinks and toilet / Found there to no water pressure in both sinks and toilet Took the sink facet apart and it to be full of saw dust and white foam Attempted to clean the facet by running water through it with the facet apart and using high pressure air facets are still clogged Recommend full replacement of both facets see attached pictures Found the toilet had no water pressure Removed the flush valve and it to be completely full of saw dust Was able to clean the debris out of the valve using a dental pick and high pressure air toilet now has correct water pressure Hold for approval and parts Additional Note : ryliefayth@gmail.com, 2025-11-14 12:53:23 :: Need auth to order both faucets for replacement.				
	Model#	Dlr Sub Hrs	1.50	Sub Labor Amt	\$285.00
Serial#	Appr Hrs	1.00	Appr Labor Amt	\$190.00	

Notes

Wrong code was used
I have adjusted the time the dealer has requested to replace; replacement is approved as described by the dealer. This authorization is pending ALL requirements of repair code have

been met.

Part Line# 1	Item #		Description			
	F100811573		*** NO LONGER AVAILABLE*** USE F100850561, WATERFALL BATHROOM FAUCET, BLACK MATTE RETAIL PKG, *REPLACEMENT FOR F100400026, 2021090599			
	Model #		Serial #		Part tag	
	Sub Qty	2.00	Sub Dlr Price	\$375.55	Sub Freight	\$17.75
	Appr Qty	2.00	Appr Dlr Price	\$375.55	Appr Freight	\$17.75
	Notes					

Submitted	Labor Amt		\$817.00	Approved	Labor Amt		\$646.00
	Parts & Freight		\$730.14		Parts & Freight		\$723.67
	Total		\$1,547.14		Total		\$1,369.67

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	