

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0008794	<b>CLAIM STATUS</b>	Paid
<b>MYERS RV CENTER INC</b>		<b>CLAIM</b>	2603804
<b>12024 CENTRAL AVE S.E.</b>		<b>CLAIM ORIGIN</b>	WEB
<b>ALBUQUERQUE, NM 87123</b>		<b>ORIGINAL CLAIM ID</b>	
<b>USA</b>		<b>VIN</b>	5ZT2TRTB8SB525587
		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$190.00	<b>SITE/WAREHOUSE</b>	048 / 048B
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	TRT28BHS
<b>MARCUS ROMERO</b>		<b>DEALER RO #</b>	73008
<b>4 Capulin Ln</b>		<b>CLAIM START DATE</b>	03/09/2026
<b>Santa Fe, NM 87501</b>		<b>CLAIM END DATE</b>	04/22/2026
<b>USA</b>			
<b>Retail Date of Purchase</b>	03/23/2026	<b>WARRANTY EXPIRATION DATE</b>	03/23/2027

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	10-11-24-00-000205	Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Repair/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : stephanie@dealer-advisors.com, 2026-03-09 16:11:35 :: Complaint: Slide will not open or close properly. Cause: Dirty seals and debris on slide causing malfunction Correction: Clean, lubricate and adjust.			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	<b>1.00</b>	<b>Sub Labor Amt \$190.00</b>	
<b>Serial#</b>	<b>Appr Hrs</b>	<b>1.00</b>	<b>Appr Labor Amt \$190.00</b>	
	<b>Notes</b>			
	From the photos, I can't decide if this is the same slide as line 2. Can you verify if it is the same or different slide? AK			
	It is the same slide. This is for the top and bottom seals, they're dirty and causing it to not operate properly.			
	Authorized for 1.0 hour to repair slide seals to allow slide to operate correctly. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. NVCB. AK			

### Labor

<b>Line# 2</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	10-11-01-00-000205	Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Replace/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : stephanie@dealer-advisors.com, 2026-03-09 16:13:05 :: Complaint: Vertical wiper seals damaged on both sides on slide exterior Cause: Seals are damaged Correction: Replace slide seals, 20 feet of BAL exact slide wiper seals			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	<b>3.00</b>	<b>Sub Labor Amt \$570.00</b>	
<b>Serial#</b>	<b>Appr Hrs</b>	<b>2.00</b>	<b>Appr Labor Amt \$380.00</b>	
	<b>Notes</b>			
	From the photos, I can't decide if this is the same slide as line 1. Can you verify if it is the same or different slide? AK			
	It is the same slide. This is for the vertical seals, they are damaged.			
	Excessive amount requested. Authorized for 2.0 hour to R/R vertical wiper seals that were damaged. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. NVCB. AK			

### Part

<b>Line# 1</b>	<b>Item #</b>	<b>Description</b>
	F100422327	SEAL, WIPE WITH SMALL TRACK, CABLE SLIDE, BLACK,FLAT SEAL, WIPE WITH SMALL TRACK, CABLE SLIDE, BLACK,FLAT   GEN 5 & GEN 5.5,   VENDOR PART #R854081 (9A-C-A-1)

