

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2640714
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	4X4TUMA23TB035532
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	080 / 080B
OWNER INFORMATION		ITEM #	UMT25RL-80
ADAM MONTOYA		DEALER RO #	73187-1
27 COUNTY RD A029		CLAIM START DATE	04/14/2026
Rainsville, NM 87736		CLAIM END DATE	04/16/2026
USA			
Retail Date of Purchase	04/17/2026	WARRANTY EXPIRATION DATE	04/17/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description
	30-92-01-00-003956	RV Safe CO & LP Detector - Interior/Interior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-04-14 09:21:40 :: Complaint: LP alarm is not working correctly Cause: LP alarm is defective Correction: Replace LP alarm

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00

Notes

changed to a more suitable code for this repair. Thank you.

Part

Line# 1	Item #		Description			
	F100400320		LP/CARBON MONOXIDE DETECTOR W/O BRACKET *RVCOLP-2B* LP/ CARBON MONOXIDE DETECTOR W/O BRACKET *RVCOLP-2B*			
	Model #		Serial #		Part tag	
					0000410705	
	Sub Qty	1.00	Sub Dlr Price	\$65.17	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$49.96	Appr Freight	\$0.00

Notes

The approved cost has been adjusted to: Dealer cost \$32.18 + state allowed mark-up of 15% for NM + OTS part allowance of 35%. In the future, please use the OTS calculator at the bottom of the policy to determine the amount Forest River will pay for the part.

Submitted	Labor Amt	\$57.00	Approved	Labor Amt	\$57.00
	Parts & Freight	\$65.17		Parts & Freight	\$49.96
	Total	\$122.17		Total	\$106.96

DEALER
SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER
SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.