

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Paid
 CLAIM 2566314
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2LNMB9T9011957
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 501 / 501
 ITEM # LNT230FK
 DEALER RO # 71720
 CLAIM START DATE 01/30/2026
 CLAIM END DATE 04/08/2026

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 60-138-24-00-001524 Termination Valve Assembly (Read Notes!!!) - Plumbing/Drainage System/
 Repair/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-30 12:10:10 :: Complaint: Black tank failed floor test, found is is leaking past the valve. Cause: Incorrect installation/component failure. Correction: Black tank valve seal leaks when termination cap is open and all tanks are full, black tank shows steady leak. Gained access to valve by removing rear portion of underbelly from rear bumper to axle, as black tank is positioned between both acles. Unit has cable valve, cable valve has to be disassembled along with propane lines and fasteners. Remove support straps for termination. Replace valve. Labor breakdown provided as previously requested on claim 2550364. 2.0 hours to remove and reinstall underbelly/refoam cut out 2.0 hours to remove and replace cable valve, disassemble propane lines/support straps .5 hours to perform floor test

Model#	Dlr Sub Hrs	4.00	Sub Labor Amt	\$760.00
Serial#	Appr Hrs	2.50	Appr Labor Amt	\$475.00

Notes

Could you please send a video of the leak past the valve to jwiner@forestriverinc.com?
 Unfortunately we do not have a video and are unable to get one.
 Dealer has requested more time than what is normally approved for this repair.
 1.0-underbelly
 1.0-cable valve
 0.5-testing

Part

Line# 1	Item #	Description		
	USERPART	1703 ATC 15 fuse		
	Model #	Serial #	Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$0.45
	Appr Qty	0.00	Appr Dlr Price	\$0.00
			Sub Freight	\$0.00
			Appr Freight	\$0.00

Notes

Line# 2	Item #	Description		
	USERPART	1.5 IN Valterra Valve		
	Model #	Serial #	Part tag	
	Sub Qty	2.00	Sub Dlr Price	\$19.78
	Appr Qty	2.00	Appr Dlr Price	\$19.78
			Sub Freight	\$0.00
			Appr Freight	\$0.00

Notes

Labor

Line# 2 **Operation Code** **Operational Description**

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-30 12:14:40 :: Complaint: Front grey tank number one failed flood test. Cause: Tank was damaged by screw at install. Correction: Had to pull front portion of underbelly, P-clips holding propane line, propane manifold, grey tank, dump handle valve and drain. Disconnected vent and drain. Removed angle iron supporting tank and inspected. Tank shows 3/16 hole on door side a quarter inch from the top shows blue arrow pointing to hole: Correction: Recommend replacing grey tank. Tank and tape used to connect ABS outlet to ABS tank will also need to be ordered. This is from claim 2550364. Labor breakdown provided as requested on previous claim. 2.0 hours to remove and reinstall underbelly/refoam cut outs 4.5 hours to remove and replace grey tank (cut vent, remove valve, flood test) .4 to remove and reinstall two scissor jacks .45 to remove and reinstall LP lines .3 drop test

Model#	Dlr Sub Hrs	7.65	Sub Labor Amt	\$1,453.50
Serial#	Appr Hrs	4.00	Appr Labor Amt	\$760.00

Notes

Dealer has requested more time than what is normally approved for this repair.

Dealer has requested more time than what is normally approved for this repair.

Removal/replacement of underbelly- 2.0

Removal/replacement of jacks- 1.0

Removal/replacement of tank- 1.0

Part

Line# 1	Item #	Description				
	USERPART	10-1693 1 1/2" Waste holding tank rubber grommet				
	Model #	Serial #	Part tag			
	Sub Qty	2.00	Sub Dlr Price	\$6.58	Sub Freight	\$0.00
	Appr Qty	2.00	Appr Dlr Price	\$6.58	Appr Freight	\$0.00

Notes

Line# 2	Item #	Description				
	USERPART	58032 1 1/2" P-trap				
	Model #	Serial #	Part tag			
	Sub Qty	2.00	Sub Dlr Price	\$7.66	Sub Freight	\$0.00
	Appr Qty	2.00	Appr Dlr Price	\$7.66	Appr Freight	\$0.00

Notes

Line# 3	Item #	Description				
	F100667878	TANK, BLACK 23"X52"X8" 30GAL END DRAIN MAKS 120003001				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$64.86	Sub Freight	\$182.10
	Appr Qty	1.00	Appr Dlr Price	\$64.86	Appr Freight	\$182.10

Notes

Submitted	Labor Amt	\$2,213.50	Approved	Labor Amt	\$1,235.00
	Parts & Freight	\$281.43		Parts & Freight	\$280.98
	Total	\$2,494.93		Total	\$1,515.98

DEALER _____ DATE _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE

All repairs described have been inspected and are satisfactory.