



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 71720
 Promised Date:
 15 JUN 25



WO #: 71720

Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 9549 2026 LONGITUDE
 230FK
 Serial#: 011957
 Chassis#: 5ZT2LNMB9T9011957
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 29 MAY 25
 Time In:

Job #1 - Internal

CHECK IN NEW UNIT

Labor

Job #	Description	Total
1	DIAGNOSIS	N/C
Subtotal for Job #1:		0.00

Job #2 - Warranty

COMPLAINT: Black tank failed flood test leak leaking past valve

CAUSE: Incorrect installation/component failure

CORRECTION: Black tank valve seal leaks. When termination cap is open and all tanks are full black tank shows steady leak. gained access to valve by removing rear portion of underbelly from rear bumper to axle as black tank valve is positioned in between both axles. Unit has cable valves cable valves had to be disassembled along with propane lines and fasteners. Removed support straps for termination
 4.50hrs

Labor

Job #	Description	Total
2	BLACK TANK	N/C

Parts

Part #	Description	Qty	Price	Total
20453	1.5IN VALTERRA VALVE	1.00	N/C	N/C
Subtotal for Job #2:				0.00

Job #3 - Warranty

COMPLAINT: Fender by entry door missing screw screws

CAUSE: missing

CORRECTION: Installed screw
 .05hrs

Labor

Job #	Description	Total
3	FENDER	N/C

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,





Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: Day nightshade in bedroom and behind recliners will not stay in the up position

CAUSE: Incorrect installation

CORRECTION: Loosend string lock and added more tension to allow for correct operation.
.20hrs

Labor

Job #	Description	Total
4	SHADE	N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: Front gray tank number one failed flood test

CAUSE: Incorrect installation during installation tank was damaged by screw.

CORRECTION: Had to pull front portion of underbelly P clips holding propane line, propane manifold, gray tank, dump handle valve and drain. Disconnected vent and drain. Removed angle iron supporting tank and inspected tank tank shows 3/16 hole on door side a quarter inch from the top image shows blue arrow pointing to hole. recommend replacing gray tank. Need to order tank and tape used to connect ABS outlet to ABS tank.
8.00hrs

Labor

Job #	Description	Total
5	GRAY TANK	N/C

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: Black tank flush does not work

CAUSE: Component failure/incorrect install installation

CORRECTION: When operating black tank flesh no water was getting to black tank. Located vacuum breaker for black tank flush and noted it was installed incorrectly. During removal and reinstallation spring failed and popped out insides of backflow preventer. Need to order new item.
.50hrs

Labor

Job #	Description	Total
6	BLACK TANK FLUSH	N/C

Subtotal for Job #6: 0.00

Job #7 - Internal

COMPLAINT: Missing Bluetooth speaker

CAUSE: Missing

CORRECTION: Need to order

Labor

Job #	Description	Total
7	SPEAKER	N/C





Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: One propane tank would not take propane. Need to replace.

CAUSE: DEFECTIVE TANK

CORRECTION: REMOVE AND REPLACE TANK
 .30HRS

Labor

Job #	Description	Total
8	LP TANK	N/C

Subtotal for Job #8: 0.00

Job #PDI1 - Internal

COMPLAINT: PRE-PDI NEW TT - 3.0

CAUSE: Stock in inspection

CORRECTION: Performed inspection and supplied list of concerns

Labor

Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

Parts

Part #	Description	Qty	Price	Total
1000	L.P. GAS	5.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #PDI1: 0.00

Job #WIN-STD - Internal

COMPLAINT: WINTERIZE STANDARD

CAUSE: Seasonal maintenance

CORRECTION: Winterize completed.

Labor

Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

Parts

Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	2.00	N/C	N/C

Subtotal for Job #WIN-STD: 0.00

Parts Total: 0.00
 Labour Total: 0.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 0.00



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 02 Feb 2026

Customer Signature : _____

Customer Work Order

W/O: 71720
Promised Date: 15 JUN 25



Customer #: 1000
MYERS "RV" CENTER,
INC.,

