



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 27069



WO #: 27069

Customer: 47602 - TRIAM RV CENTER-EAST TN  
Address: 1202 IDELL ROAD  
BULLS GAP, TN  
37711

Home Phone: 423-235-1167

Work Phone:  
Author: S.DAVIS  
Location: IH  
Invoice #:

Stock #: 11306  
Stock Desc: 2026 FW FOREST RIVER CEDAR  
CREEK 39RKB  
Model: 39RKB  
Serial #: 4X4FCRR24TS236101  
Chassis #:  
Mileage: 0  
Key #:  
Req'n #:  
License #:  
Trim:

Purchase Date:  
Date In: 27 APR 26  
Promise Date:  
Promise Time:  
Schedule Date:  
Completed:  
Warr. Date:

**Job #1 - Warranty**

COMPLAINT: NDS REAR SLIDE SEAL IS DAMAGED AND NOT LAYING AGAINST THE SLIDE WALL

CAUSE: SLIDE SEAL DAMAGED AT INSTALL, THIS WILL ALLOW WATER AND MOISTURE IN NOTED ON DAF

CORRECTION: REMOVE DAMAGED SLIDE SEAL, CLEAN AREA AND INSTALL A NEW SLIDE SEAL  
LABOR 1.0

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: THE WINDOW SCREEN BEHIND THE DOUBLE SEATING HAS A PLACE WHERE THE SCREEN IS DAMAGED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE WINDOW SCREEN  
LABOR .50

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: THE SHADE TO THE RIGHT OF THE KITCHEN SINK HAS WHITE MARKS ON OVER HALF OF THE SHADE. THESE MARKS WILL NOT JUST WIPE OFF WITH A RAG

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE SHADE  
LABOR .40

**Subtotal for Job #3: 0.00**

**Job #5 - Warranty**

COMPLAINT: WINDOW TO THE RIGHT OF DOUBLE SEATING IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA  
LABOR .20

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,



Subtotal for Job #5: 0.00

**Job #6 - Warranty**

COMPLAINT: FASCIA AROUND THE TV MANTEL IS ROUGH AND PEELING BACK

CAUSE: NOTED ON DAF

CORRECTION: SMOOTH OUT TOP WHERE IT WAS CUT AND COLOR BLEND  
LABOR .20

Subtotal for Job #6: 0.00

**Job #7 - Warranty**

COMPLAINT: THE LINO ON THE SLIDE TO THE LEFT OF THE ENTRY DOOR IS STICKING UP IN 2 PLACES. THIS WILL NOT LAY FLAT.

CAUSE: NOTED ON DAF

CORRECTION: LINO NEEDS TO BE SECURED IN PLACE CORRECTLY  
LABOR .50

Subtotal for Job #7: 0.00

**Job #8 - Warranty**

COMPLAINT: SEATING IN THE SITTING ROOM HAS A BLACK STAIN ON THE RIGHT CUSHION

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE CUSHION ON THE RIGHT SIDE  
LABOR .10

Subtotal for Job #8: 0.00

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X \_\_\_\_\_

-----  
MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 27 Apr 2026

Customer Signature : \_\_\_\_\_



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

