



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79340
Promised Date:
20 APR 26



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 79340

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 0416 CHECK WORK

Stock #: 11737

Stock Desc: 2026 TT KEYSTONE

COUGAR HALF-TON 26LBW

Chassis #: 4YDTCGM29TV505757

Serial #: 4YDTCGM29TV505757

Mileage: 0

Licence:

Invoice #:

Date In: 23 MAR 26

Promised: 30 APR 26

Date Sched:

Completed: 17 APR 26

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New PDI

CORRECTION: Torqued lugs to spec. Adjusted tire pressures to spec. Checked exterior Light function. Checked brakes and breakaway systems. Exterior inspection; checked all caulking seams. Checked sidewall vinyls. Checked windows and drains. Performed roof inspection. Installed company decals. Checked stabilizers. Checked all doors for fit and finish. Checked awning and awning light function. Checked slide function. Interior inspection; checked all cabinets, closets, and drawers. Checked all interior lights. Checked all windows and blinds. Inspected furniture. Inspected all trim and stiles. Inspected all sliding doors. Inspected flooring. Checked all outlets and charge ports. Testec alarms. Tested all appliances and sound system. Checked LP system. Checked water system

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: KITCHEN TABLE HAS A SCRATCH ON IT

CAUSE: Table scratched

CORRECTION: Remove and replace table. Had to swap over mounting system

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	PCG	25.20
Z990	MISCELLANEOUS REPAIR	PCG	10.80





Part #	Description	Qty	Price	Total
690548	DINETTE TOP	1.00	50.69	50.69

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DINETTE TOP	1.00	39.07	39.07

Subtotal for Job #1: 125.76

Job #2 - Warranty

COMPLAINT: the sensor for the panty light is not working

CAUSE: Sensor needed adjustment

CORRECTION: Moved sensor slightly. Seems to be working now

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	PCG	36.00

Subtotal for Job #2: 36.00

Job #3 - Warranty

COMPLAINT: TRIM NEXT TO THE TV IS POPPING OUT

CAUSE: Trim unglued

CORRECTION: Glued trim back into place

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	PCG	18.00

Subtotal for Job #3: 18.00

Job #4 - Warranty

COMPLAINT: THE AWNIN ARM IS A LITTLE BENT

CAUSE: Dented awning arm

CORRECTION: Replaced both awning arms. Re-wired, sealed, and tested

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	PCG	180.00
Z990	MISCELLANEOUS REPAIR	PCG	0.00
Z990	MISCELLANEOUS REPAIR	PCG	0.00

Parts

Part #	Description	Qty	Price	Total
361401	Awning - Hardware - Flatback - TT -	1.00	476.35	476.35

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-AWN HARDWARE	1.00	112.83	112.83

Subtotal for Job #4: 769.18

Job #5 - Warranty

COMPLAINT: BATHROOM DOOR TRIM IS POPPING OFF

CAUSE: Trim pulled off

CORRECTION: Popped trim back into place

Labor



Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	PCG	18.00

Subtotal for Job #5: 18.00

Job #6 - Warranty
 COMPLAINT: THE COVER FOR THE SHOWER LIGHT IS MISSING

CAUSE: Cover missing

CORRECTION: Install new cover. Had to install completely different light fixture

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	PCG	18.00
Z990	MISCELLANEOUS REPAIR	PCG	0.00

Parts				
Part #	Description	Qty	Price	Total
766439	Light - Shower - 4000K - White Bezel	1.00	28.26	28.26

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-LIGHT	1.00	12.62	12.62

Subtotal for Job #6: 58.88

Job #7 - Warranty
 COMPLAINT: THE VENT FOR THE RANGE HOOD HAS A SCRATCH

CAUSE: Factory defect

CORRECTION: Remove and replace vent

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	PCG	54.00
Z990	MISCELLANEOUS REPAIR	PCG	0.00

Parts				
Part #	Description	Qty	Price	Total
506342	Range - Hood - Vent - 1 5/8" Deep FI	1.00	7.68	7.68

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-VENT	1.00	12.57	12.57

Subtotal for Job #7: 74.25

Parts Total:	562.98
Labour Total:	360.00
Sublet Total:	0.00
Extras Total:	177.09
WORK ORDER TOTAL:	1,100.07

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

W/O: 79340
 Promised Date: 30 APR 26



Customer #: 1000
 BASDENS AMERICAN RV,



Customer Signature : _____

Date: 17 Apr 2026

W/O: 79340
Promised Date: 30 APR 26



Customer Work Order

Customer #: 1000
BASDEN'S AMERICAN RV,

