

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79248
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 56515 - MARK DIMMETT
Address: 121 RESTON DR. NEWBURGH, IN

47630

Phone: 812-893-9639

Stock Number: 11730 - 2026 CATALINA 293QBCKLE 5ZT2CAUB0TN302878

VIN: 5ZT2CAUB0TN302878 HIN:

SER#: 5ZT2CAUB0TN302878

Mileage: 0

Work Order Comp: 23 MAR 26

Auth. No:

Dealer #:

Warr. Date: 19 MAR 26

Work Order Date: 13 MAR 26

Inv #: 427741

WO # Job # Description JOB INFORMATION

79248 1 UNIT IS MISSING SOLAR CHARGE CONTROLLER
 No solar controller installed from factory
 Installed solar controller and tested

79248 2 THE TRIM AROUND THE ENTRY DOOR IS WAVY.
 When the factory installed the entry door they bent the door
 frame. The frame follows the curves in the metal. This isn't
 something we can correct and will need another entry door to
 replace. We will also need instructions or recommendations to
 prevent this from happening again. Door.
 Removed door. Cleaned off tape. Put new foam tape on new door.
 Installed new door. Siliconed top.

79248 3 THE ENTRY DOOR ASSIST HANDLE IS BENT.
 Entry door railing bent
 Remove and replace entry door railing. Installed spacers to
 prevent future issues

79248 4 THERE IS SOME EXTERIOR WOOD SHOWING AT THE FRONT SLIDE WINDOW
 Bad factory install
 Cleaned up wood and resealed

79248 12 THE COLD WATER INLET LINE TO THE WATER HEATER IS SEVERLY KINKED
 Fitting needed elbow from factory
 Removed water line. Cut out kinked portion. Installed elbow
 fitting. Water tested

Claim : 79248

```

*****
WO #      Job #      Description      JOB INFORMATION
*****
79248      13      THE KITCHEN BACKSPLASH HAS SOME WHITE MARKS ON IT
              The backsplash has a large scratch. Tried to clean and remove it
              but it will not go away. This will need replaced. Back splash
              Removed back splash and installed new one.

79248      5      THE LATCH ON THE CABINET ON THE OFF DOOR SIDE OF THE BED IS NOT
              LATCHING PROPERLY
              Poor factory install
              Cleaned up wood and reinstalled

79248      6      THE SHORE CORD INLET HAS SOME AREAS THAT IS MISSING SEALANT
              Small voids in shore cord seal
              Touched up with clear silicone

79248      7      THE ROOF HAS SOME VOIDS IN THE SEALANT
              Voids in roof dicor
              Touched voids with self leveling dicor

79248      8      SOME OF THE KITCHEN DRAWERS ARE HARD TO OPEN AND CLOSE
              Drawer rails unlubricated
              Lubricated drawer guides

79248      9      THERE IS AN EXCESSIVE AMOUNT OF WOOD PUTTY IN THE OFF DOOR WALL IN
              THE BEDROOM
              Poor factory install
              Tapped trim into place and cleaned up wood putty

79248      10     THERE IS WOOD THAT IS SPLINTERING IN THE UNDER BED STORAGE.
              Cheap wood
              Removed splinters from wood and cleaned up

79248      11     THE BUNK BED LATCH WILL NOT COME OUT OF THE WALL AND NEEDS TO BE
              RELOCATED.
              Latch mounted too close to side wall
              Move latch back and tested. Latch functions properly

79248      15     THE WOOD ON THE DOOR SIDE OF THE BUNKROOM COUCH HAS A LARGE GASH
              IN THE FINISH.
              Stile next to couch needs putty applied to the gash and scratch.
              Applied putty to the stile and removed excess.

79248      16     THE OPEN STORAGE AREA ABOVE THE FIREPLACE HAS SEVERAL EXPOSED
              STAPLES
              Fill staple holes.
              Applied putty as needed on the panels

```

Claim : 79248

 WO # Job # Description JOB INFORMATION

 Part No Job# Description PARTS Qty Price Total

 F100729266 1 SOLAR, CONTROLLER 30A PWM FLUSH M 1.00 63.09 63.09
 F100571088 2 DOOR, ENTRY GLASS BLACK, 8070R 26 1.00 586.40 586.40
 SP56-469 3 TELESCOPING RV ENTRY DOOR RAIL; M 1.00 172.89 172.89
 500627 4 CLEAR SIKASIL PLUS 1.00 11.08 11.08
 4794186 12 1/2" PEX PLASTIC COUPLER 1.00 0.08 0.08
 F100604170 13 BACKSPLASH, 14 X 24 TL GRAY HARMO 1.00 25.35 25.35

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.50 195.00 97.50
 Z990 2 MISC LABOUR CODE (EXTERNAL) 1.00 195.00 195.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.20 195.00 39.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.30 195.00 58.50
 Z990 12 MISC LABOUR CODE (EXTERNAL) 0.25 195.00 48.75
 Z990 13 MISC LABOUR CODE (EXTERNAL) 0.20 195.00 39.00
 Z990 13 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 13 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.20 195.00 39.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.20 195.00 39.00
 Z990 8 MISC LABOUR CODE (EXTERNAL) 0.20 195.00 39.00
 Z990 9 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50
 Z990 10 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50
 Z990 11 MISC LABOUR CODE (EXTERNAL) 0.30 195.00 58.50
 Z990 15 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50
 Z990 16 MISC LABOUR CODE (EXTERNAL) 0.02 195.00 3.90
 Z990 16 MISC LABOUR CODE (EXTERNAL) 0.08 195.00 15.60

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 UPS-SOLAR CONTROLLER 1.00 44.97 44.97
 FRT 13 UPS-DOOR AND BACKSPLASH 1.00 149.31 149.31

Parts Total: 858.89
 Labour Total: 750.75
 Sublet Total: 0.00
 Extras Total: 194.28

>>>> Claim Total: 1,803.92

Customer Signature: _____

Date: _____