



12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 71720  
 Promised Date:  
 no add 22



WO #: 71720

Customer Name: 1000 - MYERS "RV"  
 CENTER, INC.

Completed Date: 08 APR 26

Invoice#:

Author: BRIAN

Stock Desc: 9549 2026 LONGITUDE  
 230FK

Serial#: 5ZT2LNMB9T9011957

Date In: 29 MAY 25

Chassis#: 5ZT2LNMB9T9011957

Time In:

Miles/Hrs:

Tag#:

Purchased Date:

Warranty Date:

**Job #0 - Warranty**

CLAIMS: 2550364 / 2566314

**Subtotal for Job #0: 0.00**

**Job #1 - Internal**

CHECK IN NEW UNIT

**Labor**

Job #	Description	Total
1	DIAGNOSIS	N/C

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: Black tank failed flood test leak leaking past valve

CAUSE: Incorrect installation/component failure

CORRECTION: Black tank valve seal leaks. When termination cap is open and all tanks are full black tank shows steady leak. gained access to valve by removing rear portion of underbelly from rear bumper to axle as black tank valve is positioned in between both axles. Unit has cable valves cable valves had to be disassembled along with propane lines and fasteners. Removed support straps for termination  
 4.50hrs

**Labor**

Job #	Description	Total
2	BLACK TANK	475.00

**Parts**

Part #	Description	Qty	Price	Total
1703	ATC-15 FUSE	1.00	0.45	0.45
20453	1.5IN VALTERRA VALVE	1.00	9.89	9.89
20453	1.5IN VALTERRA VALVE	1.00	9.89	9.89

**Subtotal for Job #2: 495.23**

**Job #3 - Warranty**

COMPLAINT: Fender by entry door missing screw screws

CAUSE: missing

Customer #: 1000  
 MYERS "RV" CENTER,  
 INC.,





CORRECTION: Installed screw  
 .05hrs

<b>Labor</b>		
Job #	Description	Total
3	FENDER	19.00
<b>Subtotal for Job #3:</b>		<b>19.00</b>

**Job #4 - Warranty**

COMPLAINT: Day nightshade in bedroom and behind recliners will not stay in the up position

CAUSE: Incorrect installation

CORRECTION: Loosend string lock and added more tension to allow for correct operation.  
 .20hrs

<b>Labor</b>		
Job #	Description	Total
4	SHADE	0.00
<b>Subtotal for Job #4:</b>		<b>0.00</b>

**Job #5 - Warranty**

COMPLAINT: Front gray tank number one failed flood test

CAUSE: 1005 SEE PHOTOS When putting the unit back together gate valve leaking

CORRECTION: Upon doing the drop test the tank passed. When emptying the tank the gate valve (Volterra) is leaking through the center recommend replacing the seals inside the valve. Replaced the valve seals and it works Properly no drips

<b>Labor</b>		
Job #	Description	Total
5	GRAY TANK	760.00

<b>Parts</b>				
Part #	Description	Qty	Price	Total
10-1693	1-1/2" WASTE HOLDING TANK	2.00	3.29	6.58
	RUBBER GROMMET			
58032	1 1/2" P-TRAP	2.00	3.83	7.66
F100667878	TANK, BLACK 23"X52"X8" 30GAL END DRAIN	1.00	64.86	64.86

<b>Other Services</b>				
Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	182.10	182.10
<b>Subtotal for Job #5:</b>				<b>1,021.20</b>

**Job #6 - Warranty**

COMPLAINT: Black tank flush does not work

CAUSE: Component failure/incorrect install installation

1004 ISSUE Cause by back flow preventer not working As it was stated in my previous techs notes ,part arrived

CORRECTION: When operating black tank flesh no water was getting to black tank. Located vacuum breaker for black tank flush and noted it was installed incorrectly. During removal and reinstallation spring failed and popped out insides of backflow preventer. Need to order new item.  
 Install backflow preventer facing up.





<b>Labor</b>		
Job #	Description	Total
6	BLACK TANK FLUSH	95.00

<b>Parts</b>				
Part #	Description	Qty	Price	Total
F100081745	VALVE KIT, ANTI-SIPHON FLUSH VALVE (B&B)	1.00	13.04	13.04

**Subtotal for Job #6: 108.04**

**Job #7 - Internal**

COMPLAINT: Missing Bluetooth speaker

CAUSE: Missing

Unit one was shipped without Bluetooth speaker

CORRECTION: Need to order

Installed new Bluetooth speaker

<b>Labor</b>		
Job #	Description	Total
7	SPEAKER	N/C

<b>Parts</b>				
Part #	Description	Qty	Price	Total
F100762179	SPEAKER, BLUETOOTH/MINI SOUND BAR & BASE, MAGNETIC, WIRELESS CHARGER, BT-SPEAKER-K121	1.00	N/C	N/C

**Subtotal for Job #7: 0.00**

**Job #8 - Warranty**

COMPLAINT: Transferred to RV\*73169 on 08 APR 26

Estimate amount was 0.00

One propane tank would not take propane. Need to replace.

CAUSE:

Propane tank will not take a charge

CORRECTION:

Took pictures for warranty information

<b>Labor</b>		
Job #	Description	Total
8	LP TANK	0.00

**Subtotal for Job #8: 0.00**

**Job #PDI1 - Internal**

COMPLAINT: PRE-PDI NEW TT - 3.0

CAUSE: Stock in inspection

CORRECTION: Performed inspection and supplied list of concerns

<b>Labor</b>		
Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

<b>Parts</b>				
Part #	Description	Qty	Price	Total
1000	L.P. GAS	5.00	N/C	N/C
1703	ATC-15 FUSE	1.00	N/C	N/C



W/O: 71720  
Promised Date: 08 APR 26

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

**Subtotal for Job #PDI1: 0.00**

**Job #WIN-STD - Internal**

COMPLAINT: WINTERIZE STANDARD

CAUSE: Seasonal maintenance

CORRECTION: Winterize completed.

**Labor**

Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

**Parts**

Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	2.00	N/C	N/C

**Subtotal for Job #WIN-STD: 0.00**

Parts Total: 112.37  
Labour Total: 1,349.00  
Sublet Total: 0.00  
Extras Total: 182.10  
**WORK ORDER TOTAL: 1,643.47**

NOTICE:  
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : \_\_\_\_\_

Date: 08 Apr 2026

Customer #: 1000  
MYERS "RV" CENTER,  
INC.,

