



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$775.50

RO# : 40262 Tag# : T8920547

Check-in: Wed Mar 18, 2026 | 2:29 PM  
Ready for Pickup: Tue Apr 7, 2026 | 10:38 AM  
Promise Time: Mon Mar 23, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222  
NO@GMAIL.COM  
1025 WI-77  
Minong, WI 54859

**Pickup-Customer**  
Same as Customer  
  
**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 Keystone ASPEN  
TRAIL  
4YDTATG12 T8920547  
2 Mi In

**Service Advisor**  
KEVIN GOODIEL  
goodielk

A.	MISCELLANEOUS	DEALER STATES THERES A SCRATCHED TRIM BOARD UNDER BUNK BED	Warranty Pay	\$0.00
----	---------------	--	--------------	--------

Job added by KEVIN GOODIEL on Wed Mar 18, 2026 | 2:29 PM

1. factory scratched

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0	0	0	\$0.00	\$0.00

1. need to replace

Total Labor Sale  
\$0.00

Total Labor Cost  
\$0.00

Total Parts Sale  
\$0.00

Total Parts Cost  
\$0.00

B.	MISCELLANEOUS	DEALER STATES REPAIR/REPLACE FAN ON FURNACE	Warranty Pay	\$693.00
----	---------------	---	--------------	----------

Job added by KEVIN GOODIEL on Wed Mar 18, 2026 | 2:29 PM

1. Furnace fan very noisy while running.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$775.50

RO# : 40262 Tag# : T8920547

Check-in: Wed Mar 18, 2026 | 2:29 PM  
Ready for Pickup: Tue Apr 7, 2026 | 10:38 AM  
Promise Time: Mon Mar 23, 2026 | 6:00 PM

<b>Customer</b> linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 Keystone ASPEN TRAIL 4YDTATG12 T8920547	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$693.00  
Labor Cost: \$96.60

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	4.23	4.2	4.2	\$693.00	\$96.60

1. Pulled furnace out of camper and performed bench check. Found fan making contact with shroud. Adjusted fan so that it no longer makes contact with the shroud. Performed leak check at LP line with soapy water, then performed LP drop test. LP held at 7 inches of water column for 10 minutes. Leak check and operational check of furnace good. Fan operates quietly now.

<b>Total Labor Sale</b> \$693.00	<b>Total Labor Cost</b> \$96.60	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

<b>C. MISCELLANEOUS</b>	<b>DEALER STATES MISSING KITCHEN WINDOW BLIND TWIST ROD</b>	<b>Warranty Pay</b>	<b>\$0.00</b>
-------------------------	---	---------------------	---------------

Job added by KEVIN GOODIEL on Wed Mar 18, 2026 | 2:29 PM

1. Rod missing from factory

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00  
Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0.16	0	0	\$0.00	\$0.00

1. Installed new twist rod.

<b>Total Labor Sale</b> \$0.00	<b>Total Labor Cost</b> \$0.00	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$775.50

RO# : 40262 Tag# : T8920547

Check-in: Wed Mar 18, 2026 | 2:29 PM  
Ready for Pickup: Tue Apr 7, 2026 | 10:38 AM  
Promise Time: Mon Mar 23, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 Keystone ASPEN  
TRAIL  
4YDTATG12 T8920547

**Service Advisor**  
KEVIN GOODIEL  
goodielk

D.	MISCELLANEOUS	DEALER STATES RESEAL ROOF	Warranty Pay	\$82.50
----	---------------	---------------------------	--------------	---------

Job added by KEVIN GOODIEL on Wed Mar 18, 2026 | 2:29 PM

1. Several screws at front cap missing sealant

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$11.50

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0.4	0.5	0.5	\$82.50	\$11.50

1. Re-sealed roof in multiple areas.

<b>Total Labor Sale</b>	<b>Total Labor Cost</b>	<b>Total Parts Sale</b>	<b>Total Parts Cost</b>
\$82.50	\$11.50	\$0.00	\$0.00

Category	Sale	Cost
Labor	\$775.50	\$108.10
Parts	\$0.00	\$0.00
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
<b>Invoice Total</b>	<b>\$775.50</b>	<b>\$108.10</b>





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$775.50

RO# : 40262 Tag# : T8920547

Check-in: Wed Mar 18, 2026 | 2:29 PM  
Ready for Pickup: Tue Apr 7, 2026 | 10:38 AM  
Promise Time: Mon Mar 23, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 Keystone ASPEN  
TRAIL  
4YDTATG12 T8920547

**Service Advisor**  
KEVIN GOODIEL  
goodielk

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
D	MISC	Tue Mar 31, 2026	12:47 PM	1:11 PM	0.40 hrs	W	shurterc	0.5 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Tue Mar 31, 2026	1:13 PM	1:23 PM	0.16 hrs	W	shurterc	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Tue Mar 31, 2026	1:23 PM	4:24 PM	3.02 hrs	W	shurterc	4.2 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Wed Apr 1, 2026	8:22 AM	8:59 AM	0.62 hrs	W	shurterc	-
Tag: Regular Hour			Reason: -					
B	MISC	Wed Apr 1, 2026	11:04 AM	11:39 AM	0.59 hrs	W	shurterc	-
Tag: Regular Hour			Reason: -					
A	MISC	-	-	-	0 hrs	W	shurterc	0 hrs

**Accounting Info - Warranty**

GL Account #	Control #	Franchise	Amount
11400	40262	LINK RV	\$775.50
57200	40262	LINK RV	-\$775.50
67200	40262	LINK RV	\$108.10
14400	shurterc	LINK RV	-\$108.10

