

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 1054928
 LINK FORD & RV MINONG LLC
 1025 W HOKAH ST
 MINONG, WI 54859
 USA

CLAIM STATUS Paid
 CLAIM 2636264
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2AVEC7TG815781
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 452 / 452
 ITEM # AVT16BHX-452
 DEALER RO # 40344
 CLAIM START DATE 04/09/2026
 CLAIM END DATE 04/22/2026

Labor rate: \$165.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-100-01-00-001040 Cabinet Door Hinge, each - Interior/Cabinetry/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : alix@dealer-advisors.com, 2026-04-09 11:05:01 :: Complaint: Dealer states the top hinge on cabinet door under kitchen sink is broken. Cause: Cabinet door may have opened during transport and swung open past the designed amount. Correction: Needs new hinge.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$49.50
Serial#	Appr Hrs	0.10	Appr Labor Amt \$16.50

Notes

Is this claim for the replacement of the hinge only? Thank you Dp.
 Hello, replacement of the door is on a line below on this same PA. This line is for the hinge that needs to be replaced.
 The time requested is excessive for this repair, time adjusted. NVCB .10 to R&R the cabinet door hinge. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Part

Line# 1	Item #	Description			
	F100178910	HINGES, CABINET DOOR, MATTE BLACK (H-C78-MB)			
	Model #	Serial #	Part tag		
	Sub Qty	2.00	Sub Dlr Price	\$0.55	Sub Freight \$78.17
	Appr Qty	2.00	Appr Dlr Price	\$0.55	Appr Freight \$78.17

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 20-44-19-00-000553 Roof Moldings - Front or Rear - Exterior/Roof/Reseal/No Tread Code
Complaint, Cause, Correction
 Original Note : alix@dealer-advisors.com, 2026-04-09 11:10:14 :: Complaint: Dealer states the plumbing vent cap screw and right rear corner extrusion require reseal. Cause: Small holes in self leveling sealant from factory. Correction: Reseal plumbing vent and right corner rear extrusion.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$33.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$33.00

Notes

Part

Line# 1	Item #	Description		
	USERPART	Shop supplies - sealant		
	Model #	Serial #	Part tag	

Sub Qty	1.00	Sub Dlr Price	\$1.65	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$1.65	Appr Freight	\$0.00

Notes

Labor

Line# 3

Operation Code **Operational Description**
60-138-01-00-001530 Sewer Cap Cover - Plumbing/Drainage System/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : alix@dealer-advisors.com, 2026-04-09 11:11:55 :: Complaint: Dealer states unit did not come with a septic cap for the waste tanks. Cause: Missing part. Correction: Replace septic cap.

Model# **Dlr Sub Hrs** 0.10 **Sub Labor Amt** \$16.50

Serial# **Appr Hrs** 0.05 **Appr Labor Amt** \$8.25

Notes

The time requested is excessive for this repair, time adjusted. NVCB .05 to replace the missing sewer cap. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Part

Line# 1

Item #		Description			
60P07593A		CAP , 3" BAYONET W/ 8" STRAP (SEWER CAP), 66V20A3B			
Model #		Serial #		Part tag	
Sub Qty	1.00	Sub Dlr Price	\$2.96	Sub Freight	\$39.09
Appr Qty	1.00	Appr Dlr Price	\$2.96	Appr Freight	\$39.09

Notes

Labor

Line# 4

Operation Code **Operational Description**
30-100-01-00-001035 Cabinet Door - Interior/Cabinetry/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : alix@dealer-advisors.com, 2026-04-09 11:13:59 :: Complaint: Dealer states the cabinet door by the kitchen sink has a big scuff in it. Cause: Cabinet door may have swung open past designed amount during transport. Cabinet broke top hinge and made 2 large gouges on outside of cabinet door at bottom hinge.

Correction: Replace door. Additional Note : alix@dealer-advisors.com, 2026-04-22 08:58:10 :: Needed to replace door and left stile.

Model# **Dlr Sub Hrs** 0.40 **Sub Labor Amt** \$66.00

Serial# **Appr Hrs** 0.40 **Appr Labor Amt** \$66.00

Notes

NVCB .40 to R&R the cabinet door due to it being gouged. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Part

Line# 1

Item #		Description			
F100790863		DOOR, CABINET, 25" X 30", E/B SLAB MDF, PRAIRIE BROWN, 799397			
Model #		Serial #		Part tag	
Sub Qty	1.00	Sub Dlr Price	\$35.58	Sub Freight	\$39.09
Appr Qty	1.00	Appr Dlr Price	\$35.58	Appr Freight	\$39.09

Notes

Line# 2

Item #		Description			
F100779315		STILE, MM IPB SE, 5/8 X 3 X 109, PRAIRIE BROWN, 45G, 47095029			
Model #		Serial #		Part tag	
Sub Qty	1.00	Sub Dlr Price	\$6.10	Sub Freight	\$39.08
Appr Qty	1.00	Appr Dlr Price	\$6.10	Appr Freight	\$39.08

Notes

Submitted

Labor Amt \$165.00
Parts & Freight \$242.27

Approved

Labor Amt \$123.75
Parts & Freight \$242.27

Total \$407.27

Total \$366.02

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.