



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$907.87

RO# : 40262 Tag# : T8920547

Check-in: Wed Mar 18, 2026 | 2:29 PM
Ready for Pickup: Tue Apr 14, 2026 | 11:36 AM
Promise Time: Mon Mar 23, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG12 T8920547
2 Mi In / 2 Mi Out

Service Advisor
KEVIN GOODIEL
goodielk

A. MISCELLANEOUS	DEALER STATES THERES A SCRATCHED TRIM BOARD UNDER BUNK BED	Warranty Pay	\$148.87
-------------------------	---	---------------------	-----------------

Job added by KEVIN GOODIEL on Wed Mar 18, 2026 | 2:29 PM

1. factory scratched

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$15.50

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0	0	0	\$0.00	\$0.00
turnerl	-	0.31	0.5	0.5	\$82.50	\$15.50

1. need to replace Removed stile under rear bed, cut new and installed in place.

Parts

Parts Total Sale Amount \$12.35

Parts Total Cost Amount \$9.50

Name	Quantity	Unit Price	Sale Price	Cost Price
665670 - Stile - Square - 18mm x 3" x 96" - Carb 2 - VC - w/MDF Face - Painted Charcoal	1	\$12.35	\$12.35	\$9.50

Fees \$54.02

Code	Description	Sale Amount	Cost Amount
FF	Freight Fee	\$54.02	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$907.87

RO# : 40262 Tag# : T8920547

Check-in: Wed Mar 18, 2026 | 2:29 PM
Ready for Pickup: Tue Apr 14, 2026 | 11:36 AM
Promise Time: Mon Mar 23, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG12 T8920547

Service Advisor
KEVIN GOODIEL
goodielk

Total Labor Sale
\$82.50

Total Labor Cost
\$15.50

Total Parts Sale
\$12.35

Total Parts Cost
\$9.50

B. MISCELLANEOUS	DEALER STATES REPAIR/REPLACE FAN ON FURNACE	Warranty Pay	\$660.00
-------------------------	--	---------------------	-----------------

Job added by KEVIN GOODIEL on Wed Mar 18, 2026 | 2:29 PM

1. Furnace fan very noisy while running.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$660.00

Labor Cost: \$96.60

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	4.23	4.2	4.2	\$660.00	\$96.60
turnerl	-	0	0	0	\$0.00	\$0.00

1. Pulled furnace out of camper and performed bench check. Found fan making contact with shroud. Adjusted fan so that it no longer makes contact with the shroud. Performed leak check at LP line with soapy water, then performed LP drop test. LP held at 7 inches of water column for 10 minutes. Leak check and operational check of furnace good. Fan operates quietly now.

Total Labor Sale
\$660.00

Total Labor Cost
\$96.60

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

C. MISCELLANEOUS	DEALER STATES MISSING KITCHEN WINDOW BLIND TWIST ROD	Warranty Pay	\$16.50
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Wed Mar 18, 2026 | 2:29 PM

1. Rod missing from factory





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$907.87

RO# : 40262 Tag# : T8920547

Check-in: Wed Mar 18, 2026 | 2:29 PM
Ready for Pickup: Tue Apr 14, 2026 | 11:36 AM
Promise Time: Mon Mar 23, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG12 T8920547

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$16.50

Labor Cost: \$3.10

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0.16	0	0	\$0.00	\$0.00
turnerl	-	0	0.1	0.1	\$16.50	\$3.10

1. Installed new twist rod.

Total Labor Sale
\$16.50

Total Labor Cost
\$3.10

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

D. MISCELLANEOUS DEALER STATES RESEAL ROOF

Warranty Pay

\$82.50

Job added by KEVIN GOODIEL on Wed Mar 18, 2026 | 2:29 PM

1. Several screws at front cap missing sealant

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$11.50

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0.4	0.5	0.5	\$82.50	\$11.50
turnerl	-	0	0	0	\$0.00	\$0.00

1. Re-sealed roof in multiple areas.

Total Labor Sale
\$82.50

Total Labor Cost
\$11.50

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$907.87

RO# : 40262 Tag# : T8920547

Check-in: Wed Mar 18, 2026 | 2:29 PM
Ready for Pickup: Tue Apr 14, 2026 | 11:36 AM
Promise Time: Mon Mar 23, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG12 T8920547

Service Advisor
KEVIN GOODIEL
goodielk

	Category	Sale	Cost
	Labor	\$841.50	\$126.70
	Parts	\$12.35	\$9.50
	Sublet	\$0.00	\$0.00
	Sublet Labor	\$0.00	\$0.00
	Sublet Parts	\$0.00	\$0.00
	Fees	\$54.02	\$0.00
	Discounts	\$0.00	-
	Tax	\$0.00	-
	Deductible	\$0.00	-
	Insurance/Warranty	\$0.00	-
	Invoice Total	\$907.87	\$136.20

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
D	MISC	Tue Mar 31, 2026	12:47 PM	1:11 PM	0.40 hrs	W	shurterc	0.5 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Tue Mar 31, 2026	1:13 PM	1:23 PM	0.16 hrs	W	shurterc	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Tue Mar 31, 2026	1:23 PM	4:24 PM	3.02 hrs	W	shurterc	4.2 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Wed Apr 1, 2026	8:22 AM	8:59 AM	0.62 hrs	W	shurterc	-
Tag: Regular Hour			Reason: -					
B	MISC	Wed Apr 1, 2026	11:04 AM	11:39 AM	0.59 hrs	W	shurterc	-
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$907.87

RO# : 40262 Tag# : T8920547

Check-in: Wed Mar 18, 2026 | 2:29 PM
Ready for Pickup: Tue Apr 14, 2026 | 11:36 AM
Promise Time: Mon Mar 23, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG12 T8920547

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Tue Apr 14, 2026	10:59 AM	11:17 AM	0.31 hrs	W	turnerl	0.5 hrs
Tag: Regular Hour			Reason: -					
B	MISC	-	-	-	0 hrs	W	turnerl	0 hrs
C	MISC	-	-	-	0 hrs	W	turnerl	0.1 hrs
D	MISC	-	-	-	0 hrs	W	turnerl	0 hrs
A	MISC	-	-	-	0 hrs	W	shurterc	0 hrs

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40262	LINK RV	\$907.87
57200	40262	LINK RV	-\$841.50
67200	40262	LINK RV	\$126.70
14400	shurterc	LINK RV	-\$108.10
14400	turnerl	LINK RV	-\$18.60
54200	40262	LINK RV	-\$12.35
64000	40262	LINK RV	\$9.50
14000	40262	LINK RV	-\$9.50
76710	40262	LINK RV	-\$54.02

