



Claim CLAIM95260 (C3938509)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Changed		Date of Purchase
								Labor rate	warranty rate	
CLAIM95260 (C3938509)	40262	3/18/2026	4/14/2026	4YDTATG12T8920547	PA03985655	16105	Link Ford & RV Minong LLC 1025 Hokah St Minong, WI 54859	165.00	0.00	WARR 1/1/1970

Deny code	Item number	Name	Qty	Dealer price	Part Markup	Appr Freight	Sub Freight	Sublet	Status	
93	665670	Stile - Square - 18mm x 3" x 96" - Carb 2 - VC - w/MDF Face - Painted Charcoal	1	0	9.50	30.00 12.35	54.02	54.02	0.00	Approved
inv 5157816 Component Serial Number 815 11/19/25										
14			1	1	0.00	30.00 0.00	0.00	0.00	0.00	Approved
video available Component Model nt-20seq Component Serial Number 2544000490										
30	236692	Drape - Vertical Wands - 24"	1	0	2.24	30.00 2.91	0.00	0.00	0.00	Approved
90	102107	Sealant - Silicone - Neutral Cure - Translucent - (30/Case)	1	0	6.67	30.00 8.67	0.00	0.00	0.00	Approved

Component Serial Number air bubbles

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	3201808B	Decorative Wood Trim - Replace - per piece	0.5	0.5	82.5	0	1	0.2	Approved
<p>Complaint Dealer states there is a scratched trim board under the bunk bed. *unsure of the correct labor code as this is part of the bunk.</p> <p>Cause Factory scratched.</p> <p>Correction Replace trim/bunk piece.</p>									

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	4122102B	Furnace - Suburban - Blower Wheel	4	4	660	0	1	0.4	Approved
<p>Complaint Dealer states repair/replace fan on furnace.</p> <p>Cause Furnace fan is very noisy while running.</p> <p>Correction Pulled furnace out of camper and performed a bench check. Found fan making contact with shroud. Adjusted the fan so that is no longer makes contact with the shroud. Performed leak check at LP line with soapy water, then performed LP drop test. LP held at 7 inches of water column for 10 minutes. Leak check and operational check of furnace good. Fan operates quietly now.</p> <p>Notes Stock 660</p>									



Claim CLAIM95260 (C3938509)

Last Modified By

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	3300624B	Blind - Vertical - Wand	0.1	0.1	16.5	0	1	0.1	Approved
<p>Complaint Dealer states missing kitchen window blind twist rod. Cause Wand missing from factory. Correction Replace want.</p> <p>KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.</p>									

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	2203314D	Sealant - Roof Only Multiple Areas	0.5	0.5	82.5	0	1	0.3	Approved
<p>Complaint Dealer states reseal roof. Cause Several screws at front cap missing sealant. Correction Re-sealed roof in multiple spots.</p> <p>KRV-Spot Seal</p>									

Submitted parts & subLet	23.93	Approved parts & subLet	23.93
Submitted labor & subLet	841.50	Approved labor & subLet	841.50
Submitted freight	54.02	Approved freight	54.02
Total Submitted	<u>919.45</u>	Total approved	<u>919.45</u>