

Pre-Authorization

Pre-Authorization number

PREAUTH88958(PA03980623)

Reference no.40278

Status

Approved

Servicing Dealer 16105

Name Link Ford & RV Minong LLC

Address 1025 Hokah St
Minong, WI 54859

VIN 4YDTATL27T8920350

Retail sold on

Root		Approved		Actual	Base		Complaint/Cause/Correction
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	
5101906B	Light, Clearance & Taillight - Replace	0	0.8	0.2		1	Complaint: Dealer states the DS back taillight is cracked and will not stay attached. Cause: Taillight cover is cracked around the mounting tab causing the cover to keep falling off when the trailer is moving. Correction: Will need a new tail light with license plate holder and rewire light when part is received. KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
Pre-Authorization number: PREAUTH88958				0.2			

For paper claims only use one pre-authorization number per warranty claim form.

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.