



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$36.00

RO# : 39285 Tag# : T8920355

Check-in: Mon Sep 8, 2025 | 8:00 AM
Ready for Pickup: Tue Apr 7, 2026 | 2:37 PM
Promise Time: Sat Sep 13, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
no@email.com
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE ASPEN
TRAIL
4YDTATL26 T8920355
1 Mi In
Stock #: KS26-15

Service Advisor
BECKY DALEIDEN
beckl

A.	MISCELLANEOUS	DEALER STATES TRIM PIECE ON BACKREST OF DINETTE MISSING	Warranty Pay	\$0.00
----	---------------	---	--------------	--------

Job added by BECKY DALEIDEN on Mon Sep 8, 2025 | 8:00 AM

1. Missing trim

Op:1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0	0	0	\$0.00	\$0.00

1. Missing trim. Took photo of other side for color reference. 3'-4" is length that is needed to replace.

2. 1 hour requested

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$0.00	\$0.00	\$0.00	\$0.00

B.	MISCELLANEOUS	DEALER STATES DRIVER DAMAGE: SCRATCH ON DRIVERS SIDE TOWARDS FRONT- PICTURE ATTACHED	Internal Pay	\$36.00
----	---------------	--	--------------	---------

Job added by BECKY DALEIDEN on Mon Sep 8, 2025 | 8:00 AM

1. Scratch





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$36.00

RO# : 39285 Tag# : T8920355

Check-in: Mon Sep 8, 2025 | 8:00 AM
Ready for Pickup: Tue Apr 7, 2026 | 2:37 PM
Promise Time: Sat Sep 13, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE ASPEN
TRAIL
4YDTATL26 T8920355

Service Advisor
BECKY DALEIDEN
beckl

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$36.00
Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.27	0.3	0.3	\$36.00	\$7.20

1. I cleaned, taped and painted scratch with paint marker. Recommend new sheet new sheet metal for proper fix.

Total Labor Sale \$36.00	Total Labor Cost \$7.20	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

Category	Sale	Cost
Labor	\$36.00	\$7.20
Parts	\$0.00	\$0.00
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$36.00	\$7.20





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$36.00

RO# : 39285 Tag# : T8920355

Check-in: Mon Sep 8, 2025 | 8:00 AM
Ready for Pickup: Tue Apr 7, 2026 | 2:37 PM
Promise Time: Sat Sep 13, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE ASPEN
TRAIL
4YDTATL26 T8920355

Service Advisor
BECKY DALEIDEN
beckl

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
B	MISC	Wed Dec 31, 2025	11:31 AM	11:47 AM	0.27 hrs	I	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					
A	MISC	-	-	-	0 hrs	W	matthewl	0 hrs

Accounting Info - Internal

GL Account #	Control #	Franchise	Amount
14300	KS26-15	LINK RV	\$36.00
57300	39285	LINK RV	-\$36.00
67300	39285	LINK RV	\$7.20
14400	matthewl	LINK RV	-\$7.20

