



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79323
Promised Date:
26 MAR 26



CUSTOMER WORK ORDER

WO #: 79323

Customer: 56241 - BARTON, SUE - (812) 457-6038

Tag:

Author: BH

Location: 0330 BH TO CLOSE

Stock #: PA1639

Stock Desc: 2020 TT FOREST RIVER

CHEROKEE 274WK

Chassis #: 4X4TCKC24LX141639

Serial #: 4X4TCKC24LX141639

Mileage:

Licence:

Invoice #:

Date In: 23 MAR 26

Promised: 26 MAR 26

Date Sched:

Completed: 30 MAR 26

Warr. Date: 26 MAR 26

Job #51-1009 - Warranty

COMPLAINT: 51-1009 - INADEQUATE WHEEL-WELL SEALANT

CAUSE: Recall

CORRECTION: This unit doesn't have fender on either side it has a slideroom on each side of this unit.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	97.50

Subtotal for Job #51-1009: 97.50

Job #PDIUCTT - Internal

COMPLAINT: PDI USED CERTIFIED TRAVEL TRAILER

CAUSE: Used pdi

CORRECTION: Lug nuts torqued to spec air pressure correct in all 5 tires. Running lights and tail lights work properly brakes and Emergency Brakes work properly turned lp regulator and tanks around so they were facing camper. Exterior inspection found some voids in the sealer that I filled with clear silicone. Roof inspection found some voids in the sealer that I filled with dicor self-leveling and Dicor non sag and black Dicor non sag. Roof good now. Top of sliderooms look good. Awning fabric has a small tear in it front by the awning track. Awning lights work. Interior inspection put water in fresh tank and ran the water pump and flushed out all the lines. Hooked to city water and flushed out all the lines. Turned water heater bypass valves and filled water heater and it works properly. And put a new anode rod in water heater. Had to re stapled the board to the one by to hide the water pump and water heater. Stove works properly fireplace works properly both tvs the remotes don't work. Ac works properly. Smoke detector and lp-co detector works properly. Microwave works properly. Did my lp drop test on outside port with stove and furnace running regulator was out of adjustment so i put a new regulator on camper. System is working properly now. Dinette table cover is coming off. Tv antenna is not working properly. Pull out couch is broken. All electrical outlets work properly and USB ports work properly all windows and blinds work properly. I got the tv antenna working. And got a remote for the main tv going to get a universal for the bedroom tv

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C



Customer #: 56241
BARTON, SUE



Parts

Part #	Description	Qty	Price	Total
09-0205	MAGNESIUM ANODE ROD - SUBURBAN	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDIUCTT: 0.00**Job #FPDIUCTT - Internal**

COMPLAINT: FINAL PDI USED CERTIFIED TRAVEL TRAILER

CAUSE: Used final

CORRECTION: I just did the pdi without pulling it out of my bay. Did find fresh tank drain valve dripping so i got that replaced. Checked over everything and it all still works properly. Still waiting on the universal remote for bedroom tv. Drained black tank and gray tank and left 1/3 in fresh tank for demonstration. Lubed stabilizer jacks all 4 work properly. Unit is good to go

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	DP24 GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDIUCTT: 0.00**Job #SWAP - Internal**

COMPLAINT: SWAP CUSTOMER'S HITCHWORK

CAUSE: Swap hitch

CORRECTION: Took customers hitch brakets off their trade in and put them on there new camper. Measured and leveled the unit and got everything set and tightened down. Good to go

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #SWAP: 0.00**Job #1 - Internal**

CHECK SOFA - SEEMS LIKE A BRACKET IS BROKEN

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

W/O: 79323
Promised Date: 26 MAR 26Customer #: 56241
BARTON, SUE



Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: CHECK BATHROOM SINK FOR LEAKS

CAUSE: Check bathroom sink

CORRECTION: Inspection of the bathroom sink i found no leaks. I ran on water pump and city water and no leaks.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: TIME TO RESEAL ROOF AND SIDES

CAUSE: Fill voids and seal sidewalls

CORRECTION: On my inspection i found voids in the sealer on the roof that I filled with dicor self-leveling and Dicor non sag and black dicor non sag and sealed up the sides with clear silicone. Good to go

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING	1.00	N/C	N/C
3388	DICOR 551LSB-1 BLACK NON SAG DICOR	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - Internal

COMPLAINT: REPLACE REGULATOR

CAUSE: Replace lp regulator

CORRECTION: Could not reach recommend pressure on my gauge when doing my lp drop with stove and furnace running. There wasn't any more adjustment in the regulator so i put a new regulator on and system works properly now. And i dis a leak check on my connections

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts Part #	Description	Qty	Price	Total
06-0443	MEGR-253P LP REGULATOR 2-STAGE	1.00	N/C	N/C

Subtotal for Job #4: 0.00

Job #5 - Internal

COMPLAINT: CHECK THE TV NOT WORKING

CAUSE: Tv won't work





CORRECTION: Took antenna off the roof and tested the antenna and it works. So then i checked the cable line from antenna and it didn't have continuity. So inspected the cable from the base to antenna. Seen therehad been a screw shot through it so i cut thebad spot out and put a new end on the cable checked it again still nothing. Then i took the pannel off under the tv and found a male to male connector from antenna to tv. So i took that out and put a new end on the cable and checked it its good so then i checked the short cable from the connection to the booster it was good. So i put it together and it didnt work. So i put anewmale to male connector in andit works properly. So i used 3 new cable ends and 1 male to male connector.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Subtotal for Job #5:			0.00

Job #6 - Internal

COMPLAINT: GET NEW REMOTES FOR THE TVS

CAUSE: Bedroom tv remote

CORRECTION: Got bedroom universal remote and got it programmed and tv works properly.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JTW	N/C
Parts				
Part #	Description	Qty	Price	Total
12890	UNIVERSAL REMOTE	2.00	N/C	N/C
Subtotal for Job #6:				0.00

Job #7 - Internal

COMPLAINT: FIX THE COUCH WHERE THE FURNACE IS

CAUSE: Couch

CORRECTION: Removed couch. Removed surport boards. Cut staples off boards. Removed top panel oncouch stand. Screwed boards back to wall. Stapled back panel. Put couch back .

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Subtotal for Job #7:			0.00

Job #8 - Internal

COMPLAINT: REPLACE THE LOW POINT DRIAN

CAUSE: Fresh tank drain valve was leaking

CORRECTION: Vut leaky vale off and crimped a new drain plug on the line it works properly and no leaks

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JTW	N/C
Parts				
Part #	Description	Qty	Price	Total
10-7090	1pc 1/2" PLUG CAP	1.00	N/C	N/C
10-0926	1/2" BARB STRAIGHT ADAPT	1.00	N/C	N/C
Subtotal for Job #8:				0.00

Job #WALK - Internal

COMPLAINT: WALK THRU



CAUSE: Walk thru

CORRECTION: Walk customer around the outside of the camper and explained then went on the inside and explained the inside. Answered any questions the customer had. Vehicle didnt have a brake controller. Pulled Vehicle to service area.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #WALK: 0.00

Parts Total: 0.00
Labour Total: 97.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 97.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 03 Apr 2026

W/O: 79323
Promised Date: 26 MAR 26



Customer #: 56241
BARTON, SUE

