



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 79038  
Promised Date:  
24 FEB 26

### CUSTOMER WORK ORDER

WO #: 79038

Customer: 50528 - STOTLAR, AMY J. -  
812-306-7135

Tag:

Author: BH

Location: 0320 CHECK STATUS WITH  
JW

Stock #: 11573

Stock Desc: 2025 TT COACHMEN

CATALINA 243RBSLE

Chassis #: 5ZT2CANB6SN301263

Serial #: 5ZT2CANB6SN301263

Mileage:

Licence:

Invoice #:

Date In: 16 FEB 26

Promised: 21 FEB 26

Date Sched:

Completed: 23 MAR 26

Warr. Date: 21 FEB 26

#### Job #FPDINTT - Internal

COMPLAINT: Transferred to BAS\*79161 on 03 MAR 26

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery air pressure correct in all 5 tires. Exterior inspection cap lights work properly. But there is a dark stripe on each side. Outside refrigerator still had packing tape and foam and it wasn't plugged in. Outdoor speaker has voids that needs sealed up with silicone i did that and front cap on off door side had a void that i filled with silicone. Roof inspection found a couple voids on door side on the edge by gutter that i filled with dicor non sag. Interior inspection hooked up to city water and flushed out all the lines. Water heater works properly stove works properly microwave works properly both refrigerators work properly furnace works properly ac works properly fixed the door guide in bedroom. Drained black tank and gray tank and fresh tank. Had to tape up 3 spot on the underbelly that are hanging down.

#### Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

**Subtotal for Job #FPDINTT: 0.00**

#### Job #WINTER - Internal

COMPLAINT: Transferred to BAS\*79161 on 03 MAR 26

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

\*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE\*\*\*

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

\*\*DE-WINTERIZATION IS NOT INCLUDED\*\*

NUMBER OF GALLONS USED \_\_\_\_\_

CAUSE: Winterize unit

CORRECTION: Turned valve to winterize and pumped 2 gallons through the water pump to bathroom shower cold and hot until solution was there then repeated for bathroom faucet toilet and kitchen faucet and outside shower and spray port. Turned water heater bypass on. Depressed city inlet.

#### Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 50528  
STOTLAR, AMY J.



**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

**Subtotal for Job #WINTER:** 0.00

**Job #SWAP - Internal**

Transferred to BAS\*79161 on 03 MAR 26  
 Estimate amount was 0.00  
 SWAP CUSTOMER'S HITCHWORK

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

**Subtotal for Job #SWAP:** 0.00

**Job #1 - Internal**

COMPLAINT: Transferred to BAS\*79161 on 03 MAR 26  
 Estimate amount was 0.00  
 CHECK SLIDEOUT VINYL FLOOR

CAUSE: Vinyl floor not laying flat

CORRECTION: Curled flooring the other way to help Relax the vinyl flooring that been the other way. It worked

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

**Subtotal for Job #1:** 0.00

**Job #2 - Internal**

COMPLAINT: Transferred to BAS\*79161 on 03 MAR 26  
 Estimate amount was 0.00  
 MAKE SURE SHOWER DOORS SEAL TOGETHER

CAUSE: Shower doors not touching in the center

CORRECTION: Tried adjusting the doors every way. Got tem closer but not touching at the top. Flipped the gaskets on the doors they are better

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

**Subtotal for Job #2:** 0.00

**Job #3 - Warranty**

COMPLAINT: NOT GETTING RECEPTION FROM TV ANTENNA

CAUSE: Tv no antenna reception

CORRECTION: Took power booster out and antenna off and put my tester on the cable coming from antenna to booster and factory had the wrong cable in the wrong place on the booster. They had white cable and the purple cable flipped. So after i flipped them the Antenna works properly now. Put antenna back on and booster back in the wall. All good now

**Labor**

Code	Description	Mechanic	Total
------	-------------	----------	-------



W/O: 79038  
 Promised Date: 21 FEB 26



Customer #: 50528  
 STOLTAR, AMY J.



Z990

MISC LABOUR CODE (EXTERNAL)

JTW

111.00

Subtotal for Job #3:

111.00

**Job #4 - Warranty**

COMPLAINT: BOTH FRONT LED LIGHTS HAVE AREAS THAT ARE NOT WORKING AND NEEDS REPLACED

CAUSE: Both led cap lights had lights not working

CORRECTION: Took off old non working lights and replaced them with new ones. And then i wired them up and sealed the top. Lights work properly now.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	148.00

**Parts**

Part #	Description	Qty	Price	Total
F100625105	LIGHT, UL 108" UNDERMOUNT SMOKE 62 S	2.00	55.30	110.60

**Other Services**

Code	Description	Qty	Price	Total
FRT	UPS-LIGHTS	1.00	16.30	16.30

Subtotal for Job #4: 274.90

Customer Order

Parts Total: 110.60  
 Labour Total: 259.00  
 Sublet Total: 0.00  
 Extras Total: 16.30

**WORK ORDER TOTAL: 385.90**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 23 Mar 2026

W/O: 79038  
Promised Date: 21 FEB 26



Customer #: 50528  
STOLTAR, AMY J.

