



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 79269  
Promised Date:  
24 MAR 26

## CUSTOMER WORK ORDER

WO #: 79269

Customer: 1000 - BASDENS AMERICAN  
RV -  
Tag:  
Author: BH  
Location: 0416 CHECK WORK

Stock #: 11731  
Stock Desc: 2026 TT COACHMEN  
CATALINA 333DBDCKLE  
Chassis #: 5ZT2CAYB2TX037024  
Serial #: 5ZT2CAYB2TX037024  
Mileage: 0  
Licence:

Invoice #:  
Date In: 16 MAR 26  
Promised: 31 MAR 26  
Date Sched:  
Completed: 17 APR 26  
Warr. Date:

### Job #PDINTT - Internal

COMPLAINT: Transferred to BAS\*79425 on 31 MAR 26  
Estimate amount was 0.00  
PDI - NEW TRAVEL TRAILER

CAUSE: New pdi

CORRECTION: Lug nuts torqued to spec air pressure correct in all 5 tires. Installed a new battery box. Running lights and tail lights work properly brakes and Emergency Brakes work properly. Auto leveling system works properly. Exterior inspection found a scratch on the silver metal that i put a parts request in for. And dents in the metal and the outside corner trim on the back of this unit that i put a parts request in for. Everything else looks good. Roof inspection i found a couple voids in the sealer that I filled with dicor self-leveling and Dicor non sag. Roof is good now and top of sliderooms look good too. Awning fabric and hardware looks and works properly Awning lights work properly. Interior inspection hooked up to city water and flushed out all the lines and found rear bathroom faucet drain is not fully connected and leaks when you run water. Stove works properly microwave works properly both refrigerators work properly water heater works properly both ac units works properly furnace works properly all the lights work properly receptacles work properly all USB-C outlets work properly all windows and blinds work properly. Cabinet door between mid bathroom and bedroom door broken and i put a parts request in for a new one. Front bunk room top bunk window the paneling is cut poorly and needs a new panel. Mid bathroom toilet lids hit the cabinet can't open. Dinette trim piece screws pulled out of the bracket. Spray port hose missing so i got a new one put in camper. Had to pull unit outside to get the antenna to work. Winterize unit as well.

### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z991 | MISC LABOUR CODE (INTERNAL) | JTW      | N/C   |
| Z991 | MISC LABOUR CODE (INTERNAL) | JTW      | N/C   |
| Z991 | MISC LABOUR CODE (INTERNAL) | JTW      | N/C   |

### Other Services

| Code | Description     | Qty  | Price | Total |
|------|-----------------|------|-------|-------|
| SS   | SHOP SUPPLIES   | 0.00 | N/C   | N/C   |
| LPGI | LP - UNIT SALES | 0.00 | N/C   | N/C   |

Subtotal for Job #PDINTT: 0.00

### Job #WINTER - Internal

COMPLAINT: Transferred to BAS\*79425 on 31 MAR 26  
Estimate amount was 0.00  
WINTERIZE UNIT AND DRAIN HOLDING TANKS.  
\*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE\*\*\*  
UNITS WITH WASHING MACHINE OR ICEMAKER  
WILL BE EXTRA  
\*\*DE-WINTERIZATION IS NOT INCLUDED\*\*



Customer #: 1000  
BASDENS AMERICAN RV,



NUMBER OF GALLONS USED \_\_\_\_\_

CAUSE: Winterize unit

CORRECTION: Turned valve to winterize and pumped winterize solution through the water pump to bathroom faucet hot and cold until solution was there. Then repeated it for bathroom shower and toilet then rear bathroom faucet toilet and shower and outside shower kitchen faucet and outside spray port and washer hook up. Drained water heater and drained all tanks. Used 2 gallons of winterize solution

#### Labor

| Code | Description    | Mechanic | Total |
|------|----------------|----------|-------|
| Z990 | WINTERIZE UNIT | JTW      | N/C   |
| Z990 | WINTERIZE UNIT | JTW      | N/C   |

#### Other Services

| Code | Description   | Qty  | Price | Total |
|------|---------------|------|-------|-------|
| SS   | SHOP SUPPLIES | 0.00 | N/C   | N/C   |

**Subtotal for Job #WINTER: 0.00**

#### Job #1 - Warranty

COMPLAINT: ONE PIECE OF METAL SIDING IS DENTED. ONE PIECE IS SCRATCHED.

CAUSE: Metal dented

CORRECTION: On inspection i found that the big top piece of metal on the rear of the unit had dentss and so did the corner trim across the top. I put in a parts request for them both

#### Labor

| Code | Description                 | Mechanic | Total  |
|------|-----------------------------|----------|--------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB       | 657.15 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB       | 79.95  |
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB       | 79.95  |
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB       | 742.95 |

#### Parts

| Part #     | Description                          | Qty  | Price | Total |
|------------|--------------------------------------|------|-------|-------|
| 6378       | 36" X 96" COACHMEN GREY METAL        | 1.00 | 80.46 | 80.46 |
| 12151      | METAL, .024 X 12 X 156 1MDM SL MET S | 1.00 | 40.05 | 40.05 |
| C01256648  | MOLDING - LONG LEG (REAR CORNER) ROO | 1.00 | 15.15 | 15.15 |
| F100588123 | DECAL, REAR COACHMEN W/ DOG #90      | 1.00 | 41.42 | 41.42 |
| F100359506 | SILICONE, NEUTRAL CURE SILICONE 10.3 | 1.00 | 13.66 | 13.66 |
| 3388       | 551LSB-1 BLACK NON SAG DICOR         | 1.00 | 8.72  | 8.72  |
| 69-8349    | N102101T SELF-LEVELING SEALER - ALPH | 2.00 | 9.05  | 18.10 |

#### Other Services

| Code | Description             | Qty  | Price  | Total  |
|------|-------------------------|------|--------|--------|
| FRT  | UPS-MOLDING & DECAL     | 1.00 | 58.54  | 58.54  |
| FRT  | FREIGHT & CRATE - METAL | 1.00 | 659.14 | 659.14 |

**Subtotal for Job #1: 2,495.24**

#### Job #2 - Warranty

COMPLAINT: THE CABINET DOOR ON THE PANTRY BETWEEN THE MASTER BEDROOM AND THE LIVING QUARTERS IS BUSTED.

CAUSE: Cabinet door broken

CORRECTION: On inspection of this unit i found that the cabinet door was broken where the washer hook ups are. I put in a parts request for a new door

W/O: 79269  
Promised Date: 31 MAR 26



Customer #: 1000  
BASDEN'S AMERICAN RV,





| Labor Code | Description                 | Mechanic | Total |
|------------|-----------------------------|----------|-------|
| Z990       | MISC LABOUR CODE (EXTERNAL) | BB       | 78.00 |

| Parts Part # | Description                          | Qty  | Price | Total |
|--------------|--------------------------------------|------|-------|-------|
| F100422429   | DOOR, CABINET FPS 10W X 18.75H M&T W | 1.00 | 18.19 | 18.19 |

| Other Services Code | Description | Qty  | Price | Total |
|---------------------|-------------|------|-------|-------|
| FRT                 | UPS-DOOR    | 1.00 | 16.77 | 16.77 |

**Subtotal for Job #2: 112.96**

#### Job #3 - Warranty

COMPLAINT: REPLACE TRIM AROUND FRONT TOP WINDOW OFF DOOR SIDE IN BUNK ROOM

CAUSE: Wall panel cut bad around window

CORRECTION: On inspection i found that the wall panel was cut poorly on the bottom left corn of the window in the top bunk. That i put a parts request in for

| Labor Code | Description                 | Mechanic | Total  |
|------------|-----------------------------|----------|--------|
| Z990       | MISC LABOUR CODE (EXTERNAL) | BB       | 144.30 |
| Z990       | MISC LABOUR CODE (EXTERNAL) | BB       | 9.75   |
| Z990       | MISC LABOUR CODE (EXTERNAL) | BB       | 235.95 |
| Z990       | MISC LABOUR CODE (EXTERNAL) | BB       | 0.00   |

| Parts Part # | Description                       | Qty   | Price | Total |
|--------------|-----------------------------------|-------|-------|-------|
| F100577960   | VINYL BOARD, 3.6MM 48" X 120" F4E | 1.00  | 73.09 | 73.09 |
| F100418113   | GA<br>TAPE, SEAM 1" GAUZE ASH     | 20.00 | 0.23  | 4.60  |

| Other Services Code | Description          | Qty  | Price  | Total  |
|---------------------|----------------------|------|--------|--------|
| FRT                 | UPS FREIGHT-PANELING | 1.00 | 166.14 | 166.14 |

**Subtotal for Job #3: 633.83**

#### Job #4 - Warranty

COMPLAINT: MISSING SPRAY PORT HOSE

CAUSE: Spry port hose missing

CORRECTION: I put a parts request in for a new spray port hose and it works properly. Good to go

| Labor Code | Description                 | Mechanic | Total |
|------------|-----------------------------|----------|-------|
| Z990       | MISC LABOUR CODE (EXTERNAL) | JTW      | 97.50 |

| Parts Part # | Description                       | Qty  | Price | Total |
|--------------|-----------------------------------|------|-------|-------|
| 09-7146      | PF26-7003 BLUE QUICK CONNECT HOSE | 1.00 | 37.41 | 37.41 |

**Subtotal for Job #4: 134.91**

#### Job #5 - Warranty

COMPLAINT: REAR BATHROOM DRAIN ISN'T CONNECTED PROPERLY

CAUSE: Rear bathroom sink drain leaks

CORRECTION: After running water and inspection of the faucet and drain i noticed that it was leaking. And they had the pipes not lined up and wasn't glued. So since the pipes wasn't lined up i had to put a 40



degree pipe fitting and mock it up and to cut my measurements on were to cut my pipe. Once I did that i used pvc primer and glue the connector in and tightened everything else up. Then i tested it for leaks. No leaks all good.

| Labor |                             |          |       |
|-------|-----------------------------|----------|-------|
| Code  | Description                 | Mechanic | Total |
| Z990  | MISC LABOUR CODE (EXTERNAL) | JTW      | 58.50 |

| Parts  |                                      |      |       |       |
|--------|--------------------------------------|------|-------|-------|
| Part # | Description                          | Qty  | Price | Total |
| 100815 | Fitting - ABS - Str Elbow - 1 1/2" - | 1.00 | 0.99  | 0.99  |

Subtotal for Job #5: 59.49

#### Job #6 - Warranty

COMPLAINT: TOILET IS OUT OF ADJUSTMENT. LIDS HIT CABINETS AND WON'T OPEN ALL THE WAY

CAUSE: Toilet

CORRECTION: Removed water line to toilet. Removed toilet. Removed screws holding down toilet flange. Pull flange up enough to cut hole bigger. Screwd back down and tested. Removed screws on flange and rotated. Screwed back down and tested. Fasten down toilet. Put water line back on.

| Labor |                             |          |       |
|-------|-----------------------------|----------|-------|
| Code  | Description                 | Mechanic | Total |
| Z990  | MISC LABOUR CODE (EXTERNAL) | BB       | 58.50 |

Subtotal for Job #6: 58.50

#### Job #7 - Warranty

COMPLAINT: NOT GETTING SIGNAL TO TV ANTENNA

CAUSE: No antenna signal

CORRECTION: Took antenna off roof and the power booster out and there was a loos cable antenna works properly now

| Labor |                             |          |        |
|-------|-----------------------------|----------|--------|
| Code  | Description                 | Mechanic | Total  |
| Z990  | MISC LABOUR CODE (EXTERNAL) | JTW      | 136.50 |

Subtotal for Job #7: 136.50

Parts Total: 351.84  
Labour Total: 2,379.00  
Sublet Total: 0.00  
Extras Total: 900.59

**WORK ORDER TOTAL: 3,631.43**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 17 Apr 2026

W/O: 79269  
Promised Date: 31 MAR 26



Customer #: 1000  
BASDEN'S AMERICAN RV,

