

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2644277
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAZB8SX034724
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$195.00	SITE/WAREHOUSE	205 / 205
OWNER INFORMATION		ITEM #	ACAT343BHTSLE
AMANDA J CLARK		DEALER RO #	79598
6850		CLAIM START DATE	04/16/2026
Evansville, IN 47711		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	05/10/2025	WARRANTY EXPIRATION DATE	05/10/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description
	RC-003-13-00-004757	25V682, 2025-545 - MISSING OVERCURRENT PROTECTION - INSPECT & REPAIR - Recall/Electrical/Relocate/No Tread Code
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2026-04-16 10:57:24 :: 25V682, 2025-545 - MISSING OVERCURRENT PROTECTION Recall Went to breaker and found it was wired incorrectly. Moved wires to correct position. Sprayed battery saver on terminals. Went inside and check 12v and 120 system to be working.	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$39.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$39.00
	Notes	
	Authorized as Requested	

Labor

Line# 2	Operation Code	Operational Description
	60-136-01-00-001480	City Water Connection - Plumbing/Fresh Water Supply/Replace/No Tread Code
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2026-04-16 10:58:40 :: CUSTOMER ADVISES THAT WATER SQUIRTS OUT OF THE CITY WATER INLET WHEN THE PUMP IS ON AND UNIT IS RUNNING OFF OF FRESH TANK. City inlet leaking Went to unit saw fresh tank was empty. Filled to 1/3 turned on pump and saw inlet was leaking. Removed inlet from unit by removing screws and foam. Took jnlet off water line. Placed new inlet on and tightened down. Turned on pump to check to see if new inlet leaked. No leaks found. Placed putty on back of inlet and secured with screws. Siliochned around inlet.	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.30	\$58.50
Serial#	Appr Hrs	Appr Labor Amt
	0.30	\$58.50
	Notes	

Labor

Line# 3	Operation Code	Operational Description
	30-102-24-00-001094	Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/ Repair/No Tread Code
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2026-04-16 10:59:33 :: THE CEILING IN THE OUTDOOR KITCHEN GETS LOOSE AND SAGS DOWN. SEE WRITER IF YOU HAVE QUESTIONS Outside kitchen Brought unit in. Saw outside kitchen ceiling panel had pulled out of staples. Grabbed liquid nails and placed on 2x4 aboce panel. Stuck panel to liquid nails. Grabbed staple gun and shot staples into panel. Placed wood putty in old staple hole sthat ripped out and new holes. Cleaned up wood putty. Panel is back in place.	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$39.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$39.00

Notes

Submitted

Labor Amt	\$136.50
Parts & Freight	\$0.00
Total	\$136.50

Approved

Labor Amt	\$136.50
Parts & Freight	\$0.00
Total	\$136.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.