



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26845



WO #: 26845

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11281
Stock Desc: 2026 TT KEYSTONE
BULLETCROSSFIRE 2530RD
Model: 2530RD
Serial #: 4YDTBLM26TD431652
Chassis #:
Mileage:0
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 17 MAR 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - Warranty

COMPLAINT: CABINETS OVER BED HAVE 2 SPOTS WHERE PAINT IS SCRATCHED/CHIPPED

CAUSE: DAMAGED AT FACTORY
NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREAS
LABOR .30

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: REAR LIGHT STRIPS ON THE LEFT AND RIGHT SIDE OF UNIT WILL NOT WORK

CAUSE: FAULTY LIGHT STRIPS ON REAR OF UNIT
LIGHTS WILL NOT COME ON

CORRECTION: REMOVE AND REPLACE BOTH LIGHT STRIP
LABOR 1.0

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: BLACK TRIM HAS PAINT ON IT ABOVE THE EXIT DOOR

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND AREA
LABOR .30

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: BEDROOM HAS 2 SCRATCHES ON IT

CAUSE: NOTED ON DAF
SCRATCHED AT BUILD

CORRECTION: COLOR AND BLEND AREA
LABOR .30

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: KITCHEN CABINETS OVER THE SINK ARE TOUCHING AND NOT CLOSING CORRECTLY

CAUSE: NOTED ON DAF

CORRECTION: ADJUST HINGE SO DOOR CLOSSES CORRECTLY
LABOR .40

Subtotal for Job #5: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 17 Mar 2026

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

W/O: 26845

