



# KEYSTONE

## Pre-Authorization

Pre- Authorization number: PREAUTH85774 (PA03977545) Reference no. 26845 Status: Approved

Servicing Dealer 8140 Name Tri-AM RV Center of East TN Address 1202 Idell Rd Bulls Gap, TN 37711 VIN 4YDTBLM26TD431652 Retail sold on

Root	Operation Description	Sublet	Sub Hours	Approved Hours	Actual hours	Qty	Base hours	Complaint/Cause/Correction
3103808A	Overhead Cabinet - Repair	0	0.3	0.2		1	0.2	<b>Complaint:</b> Cabinets over bed have 2 spots where paint is scratched/chipped <b>Cause:</b> Damaged at factory <b>Correction:</b> Fill, color, and blend areas
5102806B	Light, LED-Striplight	0	1	0.6		1	0.3	<b>Complaint:</b> Rear light strips on the left and right side of the unit will not work <b>Cause:</b> Faulty light strips on rear of unit lights will not come on <b>Correction:</b> Remove and replace both light strips
3203008A	Door - Interior - Casing (all styles)	0	0.3	0.2		1	0.1	KRV-VCB <b>Complaint:</b> Black trim has paint on it above the exit door <b>Cause:</b> Noted on DAF <b>Correction:</b> Color and blend area
3202008A	Panel - Interior Wall - Repair	0	0.3	0.2		1	0.1	<b>Complaint:</b> Bedroom wall has 2 scratches on it <b>Cause:</b> Noted on DAF <b>Correction:</b> Color and blend area
3101026B	Cabinet Door - Hinge	0	0.4	0.2		1	0.1	<b>Complaint:</b> Kitchen cabinets over the sink are touching and not closing <b>Cause:</b> Noted on DAF <b>Correction:</b> Adjust hinge so door closes correctly
Pre-Authorization number: PREAUTH85774				1.4				

For paper claims only use one pre-authorization number per warranty claim form. Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.