



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26243



WO #: 26243

Customer: 47602 - TRIAM RV CENTER-EAST TN
 Address: 1202 IDELL ROAD
 BULLS GAP, TN
 37711

Home Phone: 423-235-1167

Work Phone:
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11231

Stock Desc: 2026 DT FOREST RIVER SANDPIPER
 389HBFL

Model: 389HBFL

Serial #: 4X4TSAR2XTJ048759

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 21 OCT 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 29 APR 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: SMALL HOLES ACROSS THE HIDDEN PANTRY

CAUSE: NOTED ON DAF
 HOLES NOT FILLED AT INSTALL

CORRECTION: FILL, COLOR AND BLEND
 LABOR .20

Labor

Job #	Description	Hours	Total
1	FILL COLOR AND BLEND	0.20	35.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	5.99	5.99

Subtotal for Job #1: 40.99

Job #2 - Warranty

COMPLAINT: STILE NEXT TO MICROWAVE IS CHIPPED IN 3 PLACES

CAUSE: NOTED ON DAF

CORRECTION: FILL CHIPPED AREAS IN AND COLOR BLEND
 LABOR .30

Labor

Job #	Description	Hours	Total
2	FILLED AND COLORED	0.30	52.50

Subtotal for Job #2: 52.50

Job #3 - Warranty

COMPLAINT: STILE ABOVE PANEL AT ENTRY OF UNIT HAS THE COLOR FADED OFF.

CAUSE: NOTED ON DAF

CORRECTION: FILL AND BLEND COLOR IN THIS AREA
 LABOR .20

CLAIM DENIED

Customer #: 47602
 TRI-AM RV CENTER-EAST
 TN,



Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: WHERE THE DOOR TRIM WAS INSTALLED LEFT ROUGH HOLES AND MAKES TRIM LOOK DAMAGED

CAUSE: NOTED ON DAF

CORRECTION: SMOOTH HOLES, FILL AND COLOR BLEND
LABOR .30

Labor

Job #	Description	Hours	Total
4	SMOOTH HOLES AND COLOR BLEND	0.30	52.50

Subtotal for Job #4: 52.50

Job #5 - Warranty

COMPLAINT: SLIDING DOOR TO BEDROOM IS PEELING AT THE TOP

CAUSE: NOTED ON DAF

CORRECTION: SMOOTH AREA AND COLOR BLEND
LABOR .20

Labor

Job #	Description	Hours	Total
5	SMOOTH AND BLEND	0.20	35.00

Subtotal for Job #5: 35.00

Job #6 - Warranty

COMPLAINT: CHIPPED STILE ON WASHER AND DRYER DOOR

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Labor

Job #	Description	Hours	Total
6	FILL AND COLOR	0.20	35.00

Subtotal for Job #6: 35.00

Job #7 - Warranty

COMPLAINT: DOOR HANDLE NEXT TO KITCHEN IS SCRATCHED AND DAMAGED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE DOOR HANDLE
LABOR .30

Labor

Job #	Description	Hours	Total
7	REPLACED DOOR HANDLE	0.30	52.50

Parts

Part #	Description	Qty	Price	Total
F100282520	DOOR HANDLE	1.00	14.95	14.95

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	20.09	20.09



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #7: 87.54

W/O: 26243

Parts Total:	14.95
Labour Total:	262.50
Sublet Total:	0.00
Extras Total:	26.08
WORK ORDER TOTAL:	303.53

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 30 Apr 2026

Customer Work Order



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

