



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 27002



WO #: 27002

Customer: 47602 - TRIAM RV CENTER-EAST TN
 Address: 1202 IDELL ROAD
 BULLS GAP, TN
 37711

Home Phone: 423-235-1167

Work Phone:
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11301

Stock Desc: 2026 FW KEYSTONE ASTORIA
 3603LFP

Model: 3603LFP

Serial #: 4YDFAAU20TZ915338

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 16 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 30 APR 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: BUNK BED LADDER IS SCRATCHED

CAUSE: LADDER WAS SCRATCHED AT FACTORY

CORRECTION: FILL,COLOR AND BLEND AREA
 LABOR .20

Labor

Job #	Description	Hours	Total
1	FILL AND COLOR	0.30	52.50
Subtotal for Job #1:			52.50

Job #2 - Warranty

COMPLAINT: LIVING AREA SLIDE OUT FASCIA HAS HOLES THAT ARE VERY NOTICEABLE

CAUSE: NOTED ON DAF
 DONE AT FACTORY

CORRECTION: FILL,COLOR AND BLEND AREA
 LABOR .30

Labor

Job #	Description	Hours	Total
2	FILL AND COLOR	0.10	17.50
Subtotal for Job #2:			17.50

Job #3 - Warranty

COMPLAINT: THE CABINET HANDLE ABOVE THE TV IS CHIPPED

CAUSE: NOTED ON DAF
 CHIPPED AT INSTALL

CORRECTION: REPLACE HANDLE WITH NEW HANDLE
 LABOR .20

Labor

Job #	Description	Hours	Total
3	REPLACED HANDLE	0.10	17.50

Parts

Customer #: 47602
 TRI-AM RV CENTER-EAST
 TN,



Part #	Description	Qty	Price	Total
710962	DOOR-PULL-128MM-2TONE-MATTE BLACK/SATIN BRASS	1.00	2.28	2.28

Subtotal for Job #3: 19.78

Job #4 - Warranty

COMPLAINT: STILE IS CHIPPED ABOVE PANTRY

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA
LABOR .20

Labor

Job #	Description	Hours	Total
4	FILL AND COLOR	0.10	17.50

Subtotal for Job #4: 17.50

Job #5 - Warranty

COMPLAINT: PANTRY DOOR CHIPPED

CAUSE: NOTED ON DAF
CHIPPED AT INSTALL

CORRECTION: FILL,COLOR AND BLEND AREA
LABOR .20

Labor

Job #	Description	Hours	Total
5	FILL AND COLOR	0.10	17.50

Subtotal for Job #5: 17.50

Job #6 - Warranty

COMPLAINT: SHOWER DOOR SWEEP IS DAMAGED AND OFF AS WELL AS MISSING ONE OF THE
SHOWER SWEEPS

CAUSE: NOTED ON DAF

CORRECTION: REPLACE SHOWER SWEEPS ON DOOR
LABOR .30

Labor

Job #	Description	Hours	Total
6	REPLACED SHOWER SWEEP	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
640945	Shower - Door - Sweep - Apex Series - 64 1/2" Seal For Leading Edge Of Stationary Panels - Part I	1.00	12.35	12.35

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	44.88	44.88

Subtotal for Job #6: 144.73

Job #7 - Warranty

COMPLAINT: TOP OF DRESSER IN BEDROOM IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE THE TOP OF THE DRESSER



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



LABOR .50

Labor

Job #	Description	Hours	Total
7	REPLACED	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
741305	Trim - T-Mold - 11/16" - 6442-FACH - Fairchild - 400'/Roll	5.00	0.52	2.60

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	16.09	16.09

Subtotal for Job #7: 53.69

Parts Total: 17.23
 Labour Total: 245.00
 Sublet Total: 0.00
 Extras Total: 60.97

WORK ORDER TOTAL: 323.20

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 30 Apr 2026

W/O: 27002



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

